

JWG INTERNATIONAL PTE. LTD.

ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

TEL: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: INDIA INTERNATIONAL INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SLN4526H [YOUR INSURED] & SLZ3940M [OUR CLIENT]
ON 20/10/2021.

ESTIMATED REPAIR COSTS FOR SLZ3940M

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE HW	\$ 1,659.20	X
1PC	TAILGATE INNER TRIM BOARD HW	\$ 525.50	X
1PC	TAILGATE CENTER MOULDING HW	\$ 495.79	X
1PC	TAILGATE TOYOTA LOGO HW	\$ 72.50	X
1PC	TAILGATE PRIUS PLUS EMBLEM HW	\$ 65.90	X
1PC	TAILGATE HYBRID SYNERGY EMBLEM HW	\$ 79.62	X
1PC	TAILGATE SWITCH HW	\$ 352.90	X
1PC	TAILGATE LOCK HW	\$ 461.60	X
1PC	TAILGATE WEATHER STRIP HW	\$ 399.82	X
2PCS	TAIL LAMP LH / RH @ \$601.90 EACH HW	\$ 1,203.80	X
2PCS	TAIL LAMP PANEL LH / RH @ \$339.80 EACH HW	\$ 679.60	X
2PCS	TAIL LAMP LOWER BRACKET LH / RH @ \$209.40 EACH HW	\$ 418.80	X
1PC	REAR BUMPER distorted 1 monthy crack 524.00	\$ 1,030.59	X
1SET	REAR BUMPER CLIPS HW SH	\$ 20.00	X
2PCS	REAR BUMPER SIDE RETAINER L+R @ \$144.42 EACH SW	\$ 288.84	X
2PCS	REAR BUMPER REFLECTOR LH / RH @ \$109.33 EACH HW	\$ 218.66	X
1PC	REAR END PANEL HW	\$ 880.80	X
1PC	REAR END PANEL TOP GARNISH HW	\$ 332.40	X
1PC	SPARE WHEEL PANEL HW	\$ 1,219.48	X
2PCS	SPARE WHEEL QUARTER PANEL LH / RH @ \$698.74 EACH HW	\$ 1,397.48	X
1PC	SPARE WHEEL PANEL TOP BOARD HW	\$ 412.99	X
1PC	SPARE WHEEL PANEL TOOL BOX HW	\$ 519.80	X
2PCS	REAR FENDER LH / RH @ \$ 1,847.86 EACH HW	\$ 3,695.72	X
2PCS	REAR FENDER INNER TRIM LH / RH @ \$882.42 EACH HW	\$ 1,764.84	X

PARTS SUM: \$ 18,196.63

PARTS LESS 25%: \$ 4,549.16

PARTS TOTAL: \$ 13,647.47

524.00

1030.59

393.00

772.94

LABOUR & SPECIAL NETT ITEMS

TO SUPPLY REAR NUMBER PLATE	44	\$ 80.00	X
TO SUPPLY REVERSE SENSOR	44 Dcm	\$ 400.00	220/-
TO SUPPLY TAIL LAMP SEALANT	44	\$ 60.00	X
TO SUPPLY REAR END PANEL SEALANT	44	\$ 80.00	X
TO SUPPLY 1 PC REVERSE CAMERA	44	\$ 500.00	X
TO SUPPLY REAR FENDER SEALANT	44	\$ 80.00	X
TO SUPPLY REAR FENDER INNER TRIM CLIPS	44	\$ 50.00	X
TO SUPPLY REAR BUMPER TOP GARNISH	44 1/12	\$ 800.00	80/-
TO SUPPLY TAILGATE CENTER MOULDING CLIPS	44	\$ 50.00	X
TO SUPPLY TAILGATE INNER TRIM CLIPS	44	\$ 50.00	X
TO SUPPLY REAR BUMPER CLIPS	44	\$ 50.00	X
TO SUPPLY REAR END PANEL TOP GARNISH CLIPS	44	\$ 50.00	X
TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS		\$ 300.00	44
TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS		\$ 2,000.00	200/-
TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS		\$ 2,000.00	200/-
TO TUFF COAT DAMAGED AREAS		\$ 300.00	44
TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD		\$ 200.00	X 44
TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS		\$ 250.00	X 44
TO RNR TAILGATE WINDSCREEN TO ASSIST WORK LOAD		\$ 300.00	X 44
TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS		\$ 400.00	X 44
TO RNR REVERSE SENSOR & REVERSE CAMERA		\$ 300.00	40/-
TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS		\$ 200.00	X 44
TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS		\$ 300.00	X 44

LABOUR & S/N TOTAL: \$ 6,550.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 20,197.47

22/10/2021 @ 1700h

Not Andrew

2/5/2021

Ryan

LKK Auto

2 days

1312.94

4/5 1050.00

1353.00

4/5 1050/-

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: