

KBS MOTORSPORTS PTE LTD



YOUR REF.: SMF8666R

OUR REF.: SLV6640E

TO: AIG

CC: MOTOR CLAIMS DEPARTMENT

FAX:

*Not Notified
11 Sep @ 1500h
Recovery After Repair
3 days*

DATE: 17 March 2022
FROM: Alvin Koh
FAX: 64525333
CONTACT: 81387188
MAKE & MODEL: HONDA SHUTTLE 1.5G CVT
CHASSIS NO.: GK81200137
ENGINE NO.: L15B5460170
YEAR MADE: 2017
ACCIDENT DATE: 18 January 2021

ESTIMATE FOR VEHICLE NO.: SLV6640E

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR WINDSCREEN MOULDING <i>74.10</i>		1	\$ 184.70 ✓
2	REAR WINDSCREEN		1	\$ 1,082.60 +
3	TAILGATE <i>1092</i>		1	\$ 1,351.20 ✓
4	TAILGATE LOCK		1	\$ 498.60 X
5	TAILGATE STRIKER		1	\$ 118.90 X
6	TAILGATE CHROME TRIM		1	\$ 566.30 X
7	TAILGATE WEATHER SEAL		1	\$ 187.50 X
8	TAILGATE EMBLEM SHUTTLE <i>72</i>		1	\$ 110.90 ✓
9	TAILGATE EMBLEM HYBRID		1	\$ 105.60 X
10	TAILGATE EMBLEM HONDA <i>75</i>		1	\$ 102.80 ✓
11	TAILGATE INNER TRIM BOARD		1	\$ 787.20 X
12	TAILGATE LAMP LH		1	\$ 846.80 X
13	TAILGATE LAMP RH		1	\$ 846.80 X
14	BRAKE LAMP LH		1	\$ 995.10 X
15	BRAKE LAMP RH		1	\$ 995.10 X
16	REAR BUMPER		1	\$ 1,089.90 X
17	REAR BUMPER RETAINER LH		1	\$ 102.50 X
18	REAR BUMPER RETAINER RH		1	\$ 102.50 X
19	REAR BUMPER SIDE GRILLE LH		1	\$ 146.90 X
20	REAR BUMPER SIDE GRILLE RH		1	\$ 146.90 X
21	REAR BUMPER REFLECTOR LH		1	\$ 97.30 X
22	REAR BUMPER REFLECTOR RH		1	\$ 97.30 X
23	END PANEL TOP GARNISH		1	\$ 198.40 X
24	END PANEL		1	\$ 984.10 X

TOTAL: \$ 11,745.90
LESS 20% \$ (2,349.18)
PARTS TOTAL: \$ 9,396.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

KBS MOTORSPORTS PTE LTD
160 SIN MING DRIVE, #06-03
SIN MING AUTOCITY
t 6451 5333 f 6452 5333
COMPANY REG. NO.: 200504627K

SPECIAL NETT

BODY SEALANT

REAR NUMBER PLATE + HOLDER

REAR BUMPER CLIPS

REAR BUMPER REVERSE SENSOR

1	\$	nn	80.00	X
1	\$	sn	60.00	X
10	\$	nn	100.00	X
2	\$	sn	500.00	1

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS

TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR

TO REMOVE & INSTALL REAR BOOT LID COMPONENT TO FACILITATE REPAIR

TO REMOVE & REPLACE REAR WINDSCREEN

TO REMOVE & REPLACE BUMPER SENSORS

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

TO CHECK & RECONNECT ALL NECESSARY WIRING

TO SPRAY PAINT ON THE AFFECTED AREAS

	\$	2000	1,200.00	
	\$	nn	50.00	X
	\$	600	80.00	
	\$		120.00	✓
	\$	nn	120.00	X
	\$	150	250.00	X
	\$	150	50.00	
	\$	4400	1,000.00	

TOTAL: \$ 13,006.72

7% GST: \$ 910.47

GRAND TOTAL: \$ 13,917.19