# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD		Ref:	CS3/ASM21011089/Euy3e2
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	03/11/2021
		Code:	ASM

1.	Policy Particulars :- (THIRD PARTY CLAIM)		
Insured Veh.	SHD 3673Y	**Veh. Inspected**	SLK 7821B
Policy No.	VFX/P2419138	**Coverage ($)**	0.00
Claim No.	S1M03L0K	**Excess ($)**	0.00
Assign From	LOH CYNTHIA	**Assign Date**	29/10/2021

2.	Vehicle Particulars & Condition		
Make & Model	HONDA VEZEL	**c.c**	1496
Engine No.	HIDDEN	**Year of Reg.**	2017
Chassis No.	RU11207205	**Colour**	BLUE
Odometer	147847 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	SPORTS RIM
General	FAIR		

3.	Conditions of Tyres		
	Size	**Make**	**Balance**
R/H Front Tyre	215/60 R16	DUNLOP	4 mm
L/H Front Tyre	215/60 R16	DUNLOP	4 mm
R/H Rear Tyre	215/60 R16	DUNLOP	4 mm
L/H Rear Tyre	215/60 R16	DUNLOP	4 mm

4.	Description of Damages
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.	

5.	General Information		
Accident Date	26/10/2021	**Inspect Date / Time**	29/10/2021 (04:14 PM)
Survey held at	WEI CAR SPRAY PAINTING		
	BLK 1017 YISHUN INDUSTRIAL PARK A #01-242 SINGAPORE 768759		

5a.	Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $4,000-$5,000

5b.	Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR:	**5 Working Days**

Report Ref No. CS3/ASM21011089/Euy3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser