LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SBS Transit

SBS Transit Ltd
Soon Lee Depot
28 Soon Lee Road Singapore 628083

Mainline +65 6284 8866
Facsimile +65 6262 3055

www.sbstransit.com.sg

Company Registration No: 199206653M

DATE: 28.01.2021
DAY : Friday

Workshop Accident Repair Estimate

ACCIDENT DATE	04.11.2021	**BUS REGISTRATION NUMBER**	SBS6744Z
ACCIDENT TIME	09:49 HRS	**BUS TYPE (DD OR SD)**	SD
THIRD PARTY CLAIM AGAINST	LORRY, XD9511C		

S/No	SECTION A :		PARTS & MATERIAL COST		
	SBS6744Z, MB Citaro O530, SD, AC, 2 Axle				
	Part or Item Description		**Quantity**	**Total Cost**	
1	12013163	SCREW,PULLEY,CRANKSHAFT	5	$ 20.80	nec
2	12013163	SCREW,PULLEY,CRANKSHAFT	1	$ 3.90	nec
3	12113001	MAGNETIC CLUTCH ASSY,A/C	1	$ 2,467.40	BT
4	12153227	V-BELT 1814MM;ALT A120	1	$ 55.90	nec
5	12153232	PULLEY;ALTERNATOR	1	$ 761.80	BT
6	12153255	AIR DUCT,ALTERNATOR	1	$ 175.50	BR
7	12153258	HOSE LINE,ALTERNATOR	1	$ 120.90	TN
8	12153259	HOSE LINE,ALTERNATOR	1	$ 182.00	TN
9	12153260	HOSE LINE,ALTERNATOR	1	$ 193.70	TN
10	12202156	V BELT,WATER PUMP,ENG COOL A120	1	$ 61.10	nec
11	12205000	INTERCOOLER ASSY, MB CITARO XR ^	1	$ 975.00	x nn
12	12205000	INTERCOOLER ASSY, MB CITARO XR ^	-1	-$ 975.00	x nn
13	12205000	INTERCOOLER ASSY, MB CITARO XR ^	1	$ 3,445.00	BT
14	30117513	REAR WINDSCREEN	1	$ 1,461.20	BR
15	30117514	GUIDE SIGN;BRILLIANT SILVER	1	$ 42.90	nec
16	30117515	MERCEDES STAR-SELF ADHESIVE	1	$ 16.90	nec
17	30117516	GUIDE SIGN;BRILLIANT SILVER	1	$ 42.90	nec
18	30117530	GLASS,PANEL,RR,UPPER	1	$ 1,755.00	BR
19	30311602	BRACKET RH;RR BUMPER	1	$ 20.80	nec
20	30311604	CLEVIS PIN HEAD;RR BUMPER	1	$ 2.60	nec
21	30311604	CLEVIS PIN HEAD;RR BUMPER	1	$ 2.60	nec
22	30311605	SCREW;SPECIAL SHAPE;RR BUMPER	2	$ 1.30	nec
23	30311607	BOLT,BUMPER,REAR	2	$ 2.60	nec
24	30311608	BOLT,BUMPER,REAR	1	$ 1.30	nec
25	30600021	SIGNAL LED LIGHT;AMBER	1	$ 46.80	nec
26	30600030	TAIL LAMP ASSY;RIGHT;RR	1	$ 562.90	BR
27	30600031	EXTERIOR LAMP;RR FOGLAMP	1	$ 37.70	nec
28	30600032	LED LICENSE PLATE LAMP;RR	2	$ 104.00	BR
29	30600072	BALL PIN LH/RH;RR BUMPER	1	$ 3.90	nec
30	30600073	RETAINING CLIP LH/RH;RR BUMPER	2	$ 7.80	nec
31	30600073	RETAINING CLIP LH/RH;RR BUMPER	2	$ 7.80	nec
32	30600105	TREENAIL	2	$ 2.60	nec
33	30600164	HEXAGON NUT;OUTSIDE FLAPS	2	$ 3.90	nec
34	30600209	FLAP LESS LOCK;RR END	1	$ 3,109.60	BT
35	30600213	GAS-OPERATED SPRING;RR DOOR	2	$ 293.80	BT
				$ -	
				$ -	
			SUB-TOTAL: PARTS & MATERIAL COST	**$ 15,018.90**	

A member of COMFORTDELGRO
SERVICE CLASS
PEOPLE DEVELOPER
SGS
SAC

SBS Transit

SBS Transit Ltd
Soon Lee Depot
28 Soon Lee Road Singapore 628083

Mainline +65 6284 8866
Facsimile +65 6262 3055

www.sbstransit.com.sg

Company Registration No: 199206653M

DATE: 28.01.2021
DAY : Friday

Workshop Accident Repair Estimate

ACCIDENT DATE	04.11.2021	**BUS REGISTRATION NUMBER**	SBS6744Z
ACCIDENT TIME	09:49 HRS	**BUS TYPE (DD OR SD)**	SD
THIRD PARTY CLAIM AGAINST	LORRY, XD9511C		

S/No	SECTION A :		PARTS & MATERIAL COST		
	SBS6744Z, MB Citaro O530, SD, AC, 2 Axle				
	Part or Item Description		**Quantity**	**Total Cost**	
36	30600363	BEARING;RADIATOR	2	$ 150.80	nec
37	30600367	HEX HEAD BOLT;RADIATOR	2	$ 3.90	nec
38	30600367	HEX HEAD BOLT;RADIATOR	4	$ 9.10	nec
39	30600437	CLAMPING DISC;ENG COMPT INS;RR END	4	$ 1.30	nec
40	30600438	RUBBER BUMPER,RR END,20.6X20.6X7.6	4	$ 2.60	nec
41	30600458	GUIDE SIGN COVER;FLAP FOR REAR END	1	$ 9.10	nec
42	30600521	INSULATION;OUTSIDE FLAPS	1	$ 244.40	nec
43	30600522	INSULATION;OUTSIDE FLAPS	1	$ 89.70	nec
44	30600522	INSULATION;OUTSIDE FLAPS	1	$ 89.70	nec
45	30600743	BUMPER CENTRE,REAR BUMPER COMPL	1	$ 1,056.90	BR
46	30600745	FACE BAR,REAR BUMPER,W/RR FOGLAMP,O/S	1	$ 473.20	CUT
47	30600796	BRACKET,TOWING COVER,RR BUMPER	1	$ 266.50	BR
48	30600846	PIN,JOINT COVER,REAR BUMPER	1	$ 5.20	nec
49	30600846	PIN,JOINT COVER,REAR BUMPER	1	$ 5.20	nec
50	30600847	BRACKET,JOINT COVER,REAR BUMPER	1	$ 81.90	nec
51	30600852	RUBBER,JOINT COVER,REAR BUMPER	1	$ 1.30	nec
52	30600852	RUBBER,JOINT COVER,REAR BUMPER	1	$ 1.30	nec
53	32501244	FAN DRIVE;RADIATOR	1	$ 362.70	CUT
54	32501244	FAN DRIVE;RADIATOR	1	$ 362.70	CUT
55	32501245	RADIATOR ASSY, WATER COOLER CITARO XR ^	1	$ 2,990.00	BT
56	32501247	SEALING RING;COOLANT HOSE AND LINES;	1	$ 1.30	nec
57	32501248	VALVE,COOLANT HOSE AND LINES	1	$ 124.80	nec
58	32501257	HOSE,WATER LINE,SUB-PIPE,COOLANT HOSE	1	$ 91.00	nec
59	32501260	OIL COOLER ;COOLER MODULE ;RADIATOR	1	$ 1,393.60	BT
60	32501261	HOSE,WATER LINE,HOSE,COOLANT HOSE	8	$ 179.40	nec
61	32501262	BEARING ;COOLER MODULE ;RADIATOR	1	$ 356.20	nec
62	32501263	SEAL; RADIATOR ;COOLER MODULE ;RADIATOR	1	$ 29.90	nec
63	32501264	SEAL; RADIATOR ;COOLER MODULE ;RADIATOR	1	$ 46.80	nec
64	32501266	SEAL; RADIATOR ;COOLER MODULE ;RADIATOR	1	$ 100.10	nec
				$ -	
				$ -	
			SUB - TOTAL: PARTS & MATERIAL COST	**$ 8,530.60**	

A member of
COMFORTDELGRO

SBS Transit

SBS Transit Ltd
Soon Lee Depot
28 Soon Lee Road Singapore 628083

Mainline +65 6284 8866
Facsimile +65 6262 3055

www.sbstransit.com.sg

Company Registration No: 199206653M

DATE: 28.01.2021
DAY : Friday

Workshop Accident Repair Estimate

ACCIDENT DATE	04.11.2021	**BUS REGISTRATION NUMBER**	SBS6744Z
ACCIDENT TIME	09:49 HRS	**BUS TYPE (DD OR SD)**	SD
THIRD PARTY CLAIM AGAINST	LORRY, XD9511C		

S/No	SECTION A :		PARTS & MATERIAL COST			
	SBS6744Z, MB Citaro O530, SD, AC, 2 Axle					
	Part or Item Description		**Quantity**	**Total Cost**		
65	32501267	SEAL; RADIATOR ;COOLER MODULE ;RADIATOR	1	$	130.00	nec
66	32501268	SEAL; RADIATOR ;COOLER MODULE ;RADIATOR	1	$	49.10	nec
67	32501269	SEAL ;COOLER MODULE ;RADIATOR	1	$	74.10	nec
68	32501270	SEAL; TAIL LAMP ;COOLER MODULE ;RADIATOR	1	$	53.30	nec
69	32501287	CLAMP;COOLANT HOSES	2	$	6.50	nec
70	32501289	RUBBER MOUNT;RADIATOR	10	$	146.90	nec
71	32501290	HOSE;RADIATOR.	1	$	16.90	nec
72	32501290	HOSE;RADIATOR.	1	$	16.90	nec
73	32501309	HOSE.COOLANT HOSE AND LINES	1	$	1,053.00	BR
74	32501316	CLAMP.COOLANT HOSES & LINES	4	$	20.80	nec
75	32501333	SUPPORT.FAN DRIVE;RADIATOR	1	$	882.70	BT
76	32501337	COOLANT PIPE.COOLANT HOSES AND LINES;RAD	1	$	213.20	TN
77	90082378	STKR THANK YOU FOR GIVING WAY	1	$	2.60	nec
78				$	-	
79				$	-	
80			**SUB - TOTAL: PARTS & MATERIAL COST**	**$**	**2,666.00**	
			SUB - TOTAL: PARTS & MATERIAL COST	$	15,018.90	
			SUB - TOTAL: PARTS & MATERIAL COST	$	8,530.60	
			SUB - TOTAL: PARTS & MATERIAL COST	$	2,666.00	
			TOTAL PARTS & MATERIAL COST	**$**	**26,215.50**	

	SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)			
	Labour		$	3,489.20	
			$	-	
		TOTAL LABOUR COST	**$**	**3,489.20**	

	SECTION C :	SUMMARY		
		TOTAL REPAIR COSTS	**$**	**29,704.70**
		TOTAL DOWNTIME		**10.0 days**

NOTE:
1) Repair cost is excluding Loss of use.
2) Additional parts might be required during the course of repair.

A member of
COMFORTDELGRO