PRS Filed By: GQ | REF: CS3/CTI21008475/Guc-1

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMS 8181D

at Workshop m/s A S AUTO

of

Insured: YN 9157C

Policy No. DMCVSNA00088702000

Claims No. SNM21D204439/C02

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: $270k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMS8181D Yr Regn: 21 Mar/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MERCEDES BENZ S320L c.c 2996

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 39210 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2221622A398678 *

Gen. Cond Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40ZR20

R: 245/40ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FALKEN

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	13-08-2021

Survey held at W/S 11AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$4000 - $5000, 4 repair days.
16/8/2021	Submit PRS.
	Submit P/P $8912.46, 2 repair days. (RED 1293.18; 13%)

Date/Time, File Pass to? 1) 25/11 TYPIST

Date/Time, File Return to? 2)

: Preli. Report

: Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Invs ($)

: Weekend ($)

Report Format: TP

Labour / U.P.: $8912.46

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL