PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811

ATTN: TAN JUN HONG

Ref:	CS3/ASM21011692/Bqy3e2
Date:	14/01/2022
Code:	ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 2229J	Veh. Inspected	SKT 5377U
Policy No.		Coverage ($)	0.00
Claim No.	S1M03M7N	Excess ($)	0.00
Assign From	TAN JUN HONG	Assign Date	16/11/2021

2. Vehicle Particulars & Condition

Make & Model	FORD FOCUS HB 1.6	c.c	1596
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WF05XXGCC5FK35283	Colour	WHITE
Odometer	105396 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	6 mm
L/H Front Tyre	205/55 R16	MICHELIN	6 mm
R/H Rear Tyre	205/55 R16	MICHELIN	5 mm
L/H Rear Tyre	205/55 R16	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.

5. General Information

Accident Date	16/11/2021	Inspect Date / Time	17/11/2021 (02:35 PM)
Survey held at	KING'S AUTO REPAIR & SERVICE PTE LTD		
	176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $7,000-$8,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	**7 Working Days**

Report Ref No. CS3/ASM21011692/Bqy3e2

Inspected By

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser