COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD4777A

MAKE HYUNDAI

MODEL IONIQ

DATE: 22.11.21

MVA JUMANI

DOA: 21/13/2021

AIG (P/P)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			$459.40
1	REAR BUMPER UNDER COVER			$451.25
1	REAR BUMPER CLIPS			$22.00
1	REAR BUMPER BEAM			$394.80
1	REAR FOG LAMP			$201.50
1	ANTENNA – SMARTKEY			$40.50
	Supp			$1,569.45
	Moulding rear bumper lower	ent	4155	
			1329.65	
	SUB TOTAL		1063.72	$1,569.45
	LESS 20%			$313.89
	DISCOUNTED TOTAL			$1,255.56
	REVERSE SENSOR			135.70 $137.50 NET
	REAR NUMBER PLATE			$50.00 NET
				$187.50
			185.70	
	Labour Charge			
	PANEL BEATING		350	$400.00
	SPRAY PAINT		250	$300.00
	REMOVE / REFIX REVERSE SENSOR		80	$80.00
				$780.00
	Taufik 97495749			
	ap' 22/11/21 @315pm		630.	
	p/p Resmy before paint			
	TOTAL LABOUR			$780.00
	Taufik @ Ikhan for 2 days		1879.42	
	ESTIMATE TOTAL		2 days	$2,223.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.