

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHEOW WEE HOCK
7 ST MICHAEL'S RD
#03-04
SINGAPORE 327950

Estimate No: MC1902288
Date: 18 Nov 2021
Policy No: MT/00667022/01
Veh Reg No: SJX7839G
Make/Model: PERODUA KENARI GX

ATTN:

Your Ref No: SJX7839G
Claim Type: Third Party → *MG*
Accident Date: 17/11/2021
TP Veh Reg No: SJP7317M

Not Notch in
61 Bay 81950h
Perung After Paint

4 days

Estimate Repair Cost to Vehicle No :SJX7839G

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR WINDSCREEN MOULDING - CHECK PRICE	<i>NSP</i> 1 PC	0.0000	<i>X</i>
2 TAILGATE - CHECK PRICE	<i>BN</i> 1 PC	0.0000	<i>✓</i>
3 TAILGATE KENARI LOGO - CHECK PRICE	<i>mc</i> 1 PC	0.0000	<i>—</i>
4 TAILGATE PERODUA LOGO - CHECK PRICE	<i>mc</i> 1 PC	0.0000	<i>—</i>
5 TAILGATE INNER TRIM - CHECK PRICE	<i>sm</i> 1 PC	0.0000	<i>X</i>
6 TAILGATE LOCK - CHECK PRICE	<i>n</i> 1 PC	0.0000	<i>X</i>
7 TAILGATE RUBBER - CHECK PRICE	<i>sm</i> 1 PC	0.0000	<i>X</i>
8 REAR BUMPER - CHECK PRICE	<i>n</i> 1 PC	0.0000	<i>X</i>
9 REAR BUMPER LAMP LH & RH - CHECK PRICE	<i>sm</i> 2 PC	0.0000	<i>X</i>
10 REAR BUMPER LOWER GARNISH - CHECK PRICE	<i>Respray</i> 1 PC	0.0000	<i>X</i>
11 REAR BUMPER SIDE RETAINER LH & RH - CHECK PRICE	<i>sm</i> 2 PC	0.0000	<i>X</i>
12 REAR BUMPER CLIPS - CHECK PRICE	<i>na</i> 12 PC	0.0000	<i>X</i>
13 REVERSE SENSOR LH & RH - CHECK PRICE	<i>sm</i> 2 PC	0.0000	<i>20000</i>
14 REVERSE SENSOR RING - CHECK PRICE	<i>na</i> 2 PC	0.0000	<i>X</i>
15 REAR END PANEL - CHECK PRICE	<i>n</i> 1 PC	0.0000	<i>X</i>
16 REAR END PANEL PANEL GARNISH - CHECK PRICE	<i>sm</i> 1 PC	0.0000	<i>X</i>
17 EXHAUST PIPE TAIL - CHECK PRICE	<i>sm</i> 1 PC	0.0000	<i>X</i>
18 EXHAUST PIPE TAIL BRACKET - CHECK PRICE	<i>sm</i> 1 PC	0.0000	<i>X</i>
19 FRONT CROSSMEMBER - CHECK PRICE	<i>n</i> 1 PC	0.0000	<i>X</i>
		0.00	0.00
Special Nett			
20 INNER SEAL	1 PC	<i>na</i> 20.00	<i>—</i>
21 WINDSCREEN SEALANT	1 PC	<i>na</i> 40.00	<i>—</i>
22 NUMBER PLATE	1 PC	<i>sm</i> 35.00	<i>✓</i>
		95.00	95.00
LABOUR			
23 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>15h</i>
24 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	<i>✓</i>
25 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	<i>na</i> 350.00	<i>X</i>
26 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>50h</i>
27 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	<i>30h</i>
28 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	60.00	<i>✓</i>

108
Zila
Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHEOW WEE HOCK
7 ST MICHAEL'S RD
#03-04
SINGAPORE 327950

Estimate No: MC1902288
Date: 18 Nov 2021
Policy No: MT/00667022/01
Veh Reg No: SJX7839G
Make/Model: PERODUA KENARI GX

ATTN:

Your Ref No: SJX7839G
Claim Type: Third Party
Accident Date: 17/11/2021
TP Veh Reg No: SJP7317M

Estimate Repair Cost to Vehicle No :SJX7839G

Description	Quantity	List Price	Amount
		S\$	S\$
29 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	500
30 TO SPRAY TAILGATE,REAR BUMPER,REAR END PANEL.	1 PC	700.00	600
31 **SUPPLIER NOT ABLE TO PROVIDE PARTS PRICES**	1 PC		
		2,190.00	2,190.00
		Total	S\$ 2,285.00
		Add GST @ 7%	159.95
		Total Amount Payable	S\$ 2,444.95

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FOUR HUNDRED FORTY FOUR AND CENTS NINETY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

Zita
Ah Lim Motor Company

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: