LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805   Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21012045/KVF3E2

Date: 07/07/2022

REFERENCE

Insured/Claimant:	SETSCO SERVICES PTE LTD	Policy No:	D20MFL0000790_01	
Date of Loss:	20/11/2021	Nature of Claim:	OD	Claim No: MFL2021D0005154

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**GBJ5180D**		
Make & Model:	NISSAN NV350 CARAVAN, 2.5 5AT (A)	Engine No:	YD25042949B
Reg. Date:	10/05/2019 (Man. Year: 2018)	Chassis No:	JN1MC2E26Z0030887
Colour:	White	Odometer:	62568 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	S$57,000.00		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	DURATURN 9 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	DURATURN 9 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	989.10	799.20	189.90	19.20
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,030.00	1,000.00	1,030.00	50.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**3,030.10**	**1,810.20**	**1,219.90**	**40.26**
- Excess (S$)	0.00	500.00	-500.00	
(S$)	3,030.10	1,310.20	1,719.90	56.76
+ GST 7.00/7.00% (S$)	212.11	91.71	120.40	56.76
Nett Amount (S$)	**3,242.21**	**1,401.91**	**1,840.30**	**56.76**

INSPECTION

Date of Assignment:	29/11/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	14/12/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 14 Dec 2021)
Parts:	N/A	NISSAN NV350 CARAVAN 2.5 5AT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ5180D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***REAR BUMPER**	Dented/Deep Cut	600.00 F	*600.00 F
2	1		***REAR BUMPER CLIP**	Necessary	14.00 F	*14.00 F
3	1		***REAR END PANEL**	Repair	211.00 F	*- F
4	1		***LH TAILLAMP**	Broken	274.00 F	*274.00 F

F=Franchise part.

	Repairer's	Amount
Sub Total (S$)	**1,099.00**	**888.00**
- Add. Disc. on L,N Items 10.00/10.00% (S$)	109.90	88.80
Total Parts (S$)	**989.10**	**799.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	**OD/TP Case (Insurer)**	11.00	11.00
		Sub Total (S$)	**11.00**	**11.00**

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**TO CUT WELD REAR END PANEL,REPAIR LH REAR SIDE PANEL ,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS**	New	1,000.00	500.00
2	**TO PUTTY ,RESPRAY ON LH REAR SIDE PANEL,REAR BUMPER END PANEL,TAILGATE AND AFFECTED AREAS.**	New	1,000.00	500.00
3	**CHECK LIGHTING AND WIRING**	New	30.00	0.00
	Gross Labour Cost (S$)		**2,030.00**	**1,000.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >