CYCLE & CARRIAGE

VEHICLE NO : SMZ 4316 Y

MODEL : MIT/OUTLANDER 2.0 STYLE

WIP : 17992

Material	: $	1,734.81
Labour	: $	2,245.00
Sub-Total	: $	3,979.81
Less 2% Disc	: $	—
Less Excess	: $	300.00
Total	: $	3,679.81
GST 7%	: $	257.59
Grand Total	: $	3,937.40
Finalise By/Date :	Larry on 26/01/22	

☑ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK ___05___ WORKING DAYS + 2 days (wk.end)

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339   Tel: 65684555 Fax: 65691056

MITSUBISHI MOTORS

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 **Contact No** 6419 1892	Cust No/Name	KCV19048/MOHAMED YUSRI BIN MOHAMED YUSOF
	Reg No/Reg Date	SMZ4316Y / 27/04/2021
	Date In/Mileage	06/01/2022/ 9592
	Chassis/Package	GF7W0700793 /#F
	Engine No	4J11CQ8847
	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)
06/01/2022	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	25/01/2022/ 16:53	BLE	884 / Lauro Songcuan	17992

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000				
RENEW LH FRONT DOOR & LH REAR DOOR, REPAIR ROCKER PANEL BODY KIT				900.00
E PNT98000				
SPRAY PAINT LH FRONT DOOR, LH REAR DOOR & LH SIDE SKIRT				875.00
E PNT88000				
REMOVE & REFIT LH FRONT DOOR COMPONENTS				120.00
E PNT88000				
REMOVE & REFIT LH REAR DOOR COMPONENTS				120.00
A 54900099				
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901				
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY				
SUPPLY BODY PANEL SEALANT				60.00
M SUNDRY				
SUNDRIES				20.00
X EXC				
EXCESS				-300.00
X PANEL ASSY,FR DOOR,LH	1.00	930.00	23.00	716.10
X PANEL ASSY,RR DOOR,LH	1.00	851.00	23.00	655.27
X TAPE,FR DOOR SASH,LH	1.00	42.00	23.00	32.34
X TAPE,RR DOOR SASH	1.00	42.00	23.00	32.34
X TAPE,RR DOOR SASH	1.00	42.00	23.00	32.34
X GARNISH,FR DOOR,LH	1.00	182.00	23.00	140.14
X GARNISH,RR DOOR,LH	1.00	*164.00	23.00	126.28
Z TEXT				
AIG - OD CLAIM				
SURVEY: RASUL (LKK) 06/01/2022				
DOA: 29/11/2021				
05 DAYS				

(handwritten) 158.00

(handwritten) * change price

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	1,734.81			
Labour	2,165.00		Nett	3,679.81
Standard Menu	0.00	7% GST on 3679.81		257.59
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	3,937.40
Sundry/Others	-220.00			
Total(w/o GST)	3,679.81			

This is not an official tax invoice.
This is a computer generated document, no signature is required.

Page 1 of 1

Item	Setting	
	Information	
M.U.T.-3 Version	SEW21121-00	
V.C.I. Version	B179	
Vehicle Information	DBA-GF7W XTXX 2020MY	

Ref No: 8MZ43164
Before to using MUT-3x VCI unit to check all
to see found

2022.01.13

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AUDIO (Display Audio)	AUDIO_8D080002		No DTCs	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		No DTCs	
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
OSS	OSS_9588000B		No DTCs		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000		No DTCs		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080000		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A 0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0 080000		Non-equipped System or Communication Error		