# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R  GST Reg. No. 19-9607198-R

## PRE-REPAIR INSPECTION REPORT

| AXA INSURANCE PTE LTD | | Ref: | CS3/ASM21012218/Gvy3e2 |
|---|---|---|---|
| 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 | | Date: | 06/12/2021 |
| ATTN: KOH JANICE | | Code: | ASM |

| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | |
|---|---|---|---|---|
| | Insured Veh. | SHC 7001R | Veh. Inspected | SCM 6200X |
| | Policy No. | P2419140 | Coverage ($) | 0.00 |
| | Claim No. | S1M03N3V | Excess ($) | 0.00 |
| | Assign From | KOH JANICE | Assign Date | 01/12/2021 |

| 2. | Vehicle Particulars & Condition | | | |
|---|---|---|---|---|
| | Make & Model | HONDA CRV 2.0L | c.c | 1997 |
| | Engine No. | HIDDEN | Year of Reg. | 2010 |
| | Chassis No. | JHLRE2850AC200635 | Colour | WHITE |
| | Odometer | 138534 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| | General | GOOD | | |

| 3. | Conditions of Tyres | | | |
|---|---|---|---|---|
| | | Size | Make | Balance |
| | R/H Front Tyre | 225/65 R17 | MICHELIN | 6 mm |
| | L/H Front Tyre | 225/65 R17 | MICHELIN | 6 mm |
| | R/H Rear Tyre | 225/65 R17 | MICHELIN | 6 mm |
| | L/H Rear Tyre | 225/65 R17 | MICHELIN | 6 mm |

| 4. | Description of Damages |
|---|---|
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. |

| 5. | General Information | | |
|---|---|---|---|
| | Accident Date | 26/11/2021 | Inspect Date / Time | 02/12/2021 ( 05:30 PM ) |
| | Survey held at | AUTO BEST MOTOR SERVICES | | |
| | | BLK 3006 UBI ROAD 1 #01-362 SINGAPORE 408700 | | |

| 5a. | Remarks |
|---|---|
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $4,000-$5,000 |

| 5b. | Estimate Days of Repair | |
|---|---|---|
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | **6 Working Days** |

Report Ref No. CS3/ASM21012218/Gvy3e2

**Inspected By**

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser