

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com /teamautopl@gmail.com

Jashin

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SLU 8888 A**
 Model : Porsche Cayenne
 Year : 2019
 Chassis No : WP1ZZZ9YZKDA01505

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

2019

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bonnet logo	1	\$ 235.00	\$ 210.00 235.00
2	Bonnet lock	2	\$ 298.70	\$ 597.40
3	Bonnet lock upper latch	2	\$ 262.00	\$ 524.00
4	Bonnet inner rubber	1	\$ 380.00	\$ 73.50 380.00
5	Front bumper side retainer	2	\$ 134.10 192.00	\$ 268.20 384.00
6	Front bumper side carriage RH	1	\$ 178.00	\$ 60.00 178.00
7	Front bumper support top panel	1	\$ 468.50	\$ 230.00 468.50
8	Front bumper tow cover	1	\$ 102.00	\$ 95.00 102.00
9	Front bumper signal lamp RH	1	\$ 833.80	\$ 349.00 833.80
10	Front bumper signal garnish <i>RH 1</i>	2	\$ 508.60	\$ 508.60 1,017.20
11	Front bumper signal inner base garnish	1	\$ 488.00	\$ ✓ 488.00
12	Front bumper lower side garnish	2	\$ 60.00 114.60	\$ 60.00 229.20
13	Front bumper centre grille	1	\$ 1,854.00	\$ 304.60 1,854.00
14	Front bumper lower cover	1	\$ 579.40	\$ 579.40
15	Front bumper inner sponge	1	\$ 397.60	\$ 288.00 397.60
16	Front bumper reinforcement	1	\$ 1,487.70	\$ 1,487.70
17	Front bumper parking sensor <i>CTR 2</i>	4	\$ 285.00 396.20	\$ 570.00 1,584.80
18	Front bumper liscence plate	1	\$ 122.30	\$ 80.00 122.30
19	Front air duct with control	1	\$ 1,921.00	\$ 550.00 1,921.00
20	Front air duct bottom	1	\$ 843.50	\$ 136.00 843.50
21	Front air duct bottom outer garnish	1	\$ 447.00	\$ 447.00
22	Front support panel	1	\$ 2,447.90	\$ 1660.40 2,447.90
23	Front support top panel	1	\$ 1,292.60	\$ 570.00 1,292.60
24	Front support panel top garnish	1	\$ 126.10	\$ 126.10 ✓ 126.10
25	Front support panel top garnish rubber	1	\$ 89.00	\$ 89.00
26	Front engine side cover	1	\$ 187.00	\$ 187.00
27	Front brace panel	1	\$ 342.50	\$ 342.50
28	Air intake duct	1	\$ 176.00	\$ 176.00
29	Headlamp	2	\$ 5138.00 8,122.50	\$ 10,276.00 16,245.00

NECV
NDX
DLV
NECV
BRV
DDV
CUTV
BRV
BRV
BRV
CUTV
BRV
NDX
BRV
NDX
SCV
MIS
BRV
BRV
NSX
DDV
DDV
BRV
NSX
NDX
NDX
NDX
BRV

30	Headlamp bracket	RH 1	2	\$	205.00	\$ 315.70	410.00	BRV
31	A/C condenser		1	\$	2,864.40	\$	2,864.40	NDX
Parts Sub Total :						\$ 24,446.61	38,854.90	
5% Discount :						\$ 1,222.30	1,942.75	
PARTS TOTAL :						\$	36,912.16	

23,224.28

25,224.28

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Bonnet (TECHART) Carbon Fibre	1	\$ 15,800.00	\$ 14,500.00 15,800.00
3	Front bumper (TECHART)	1	\$ 10,790.00	\$ 9,500.00 10,790.00
4	Front bumper lower (TECHART)	1	\$ 6,700.00	\$ 6,000.00 6,700.00
5	Front bumper diffuser (TECHART)	1	\$ 3,880.00	\$ 3,500.00 3,880.00
6	Front bumper difusser centre garnish	1	\$ 680.00	\$ 500.00 680.00
7	Front bumper difusser centre bracket	1	\$ 500.00	\$ 450.00 500.00
8	Front bumper clips	1	\$ 60.00	\$ 60.00
9	Front bumper lower clips	1	\$ 60.00	\$ 60.00
10	Front support panel top garnish clips	1	\$ 60.00	\$ 30.00 60.00
11	Front bumper parking sensor seal CTR 2	4	\$ 35.00 48.00	\$ 70.00 192.00
12	A/C fluid	1	\$ 100.00	\$ 100.00
13	Radiator coolant	1	\$ 120.00	\$ 120.00
14	Front number plate w/casing	1	\$ 80.00	\$ 60.00 80.00
SPECIAL NETT TOTAL :				\$ 39,102.00

29,210.00

Nos.	LABOUR	S\$	
1	R&R front bumper parking sensor	\$ 60.00	150.00
2	R&R A/C condenser	\$	150.00
3	R&R radiator	\$	150.00
4	Check wiring	\$	150.00
5	Upholstery	\$	300.00
6	Diagnostic & reset fault code	\$ 120.00	300.00
7	Panel beating	\$ 800.00	1,600.00
8	Rust proofing	\$	200.00
9	Spray painting	\$ 600.00	1,600.00
LABOUR TOTAL :		\$	4,600.00

1580.00

PARTS TOTAL : \$ 36,912.16
SPECIAL NETT TOTAL : \$ 39,102.00
LABOUR TOTAL : \$ 4,600.00
GRAND TOTAL : \$ 80,614.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LS 43,200/2

TGum him

14/2/2022

Parts 23,224.28
s N 29,210.00
Labour 1,580.00
54,014.28
@2090 10,802.86
43,211.42

Survey 7/12/2021
TGum him
1700 hrs

Resurvey 9/12/2021
TGum
1700 hrs

Lump sum repair
Repair days 7