ASS. REC. BY: Kenneth

REF: AG/210124041/kqf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Choon Hock

of _____

Insured: _____

Policy No. _____

Claims No. 3966024472SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 04/22 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCW 8675T Yr Regn: 04, 99

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Honda Civic VTi c.c 1493

Colour M. Gold A/C: Insured / Std / NI / NA

Sp.Reading 109528 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMEK3670X S205586

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modl : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/45ZR16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Kumho

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm
D.O.A.	4/12/21	D.O.I.	8/12/2021

Survey held at ✓

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	
	Kenneth confirm LS $1600, 3 days (Red $1754, 52%)

Date/Time, File Pass to? 17/12 Typist

1)

Date/Time, File Return to?

2)

☐ : Prell. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Survey Fee:

Transportation: ___ $ - RS. ___ SI

Parking

Others

TOTAL

Report Format : MER-TP

Lump Sum ~~I.B.I.~~ ($ 1600)

CHOON HOCK MOTOR TRADING CO

Not Authorised
L/Sing &
Resurvey After Paint
3days

6 December 2021

ESTIMATE REPAIR BILL ON SCW8675T HONDA CIVIC AUTO

1 pce rear lamp LH		$ 350.00
1 pce rear lamp lower panel LH		$ 80.00
1 pce rear bumper assy.		$ 750.00
1 pce rear bumper retainer LH		$ 75.00
1 pce rear panel		$ 380.00
1 pce rear boot logo 'H'		$ 45.00
1 pce 'CIVIC' logo		$ 70.00
1 pce 'VTI' sticker		$ 30.00
		$1,780.00
	less 20%	$ 356.00
		$1,424.00

Labour

Rustproofing	$ 80.00 2hr
Wiring	$ 50.00 2hr
Panel beating	$ 900.00 35hr
Spray painting	$ 900.00 50hr
Total amount:	$3,354.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

From: Jacq Au appletree.au@gmail.com
ubject: Ah Xiong
Date: 7 December 2021 at 4:34 PM
To: Au Cheong choonhockmotor@gmail.com

SD0821C60001 / Ding Auto Pte Ltd
ENTRY DATE & TIME: 06/12/2021 16:14 (SGT)
SUBMITTED BY: Henry
VERSION: 1 (06/12/2021 16:14 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE
1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	06/12/2021 16:14 (SGT)
Date of Accident	04/12/2021 18:00 (SGT)
Exact Location of Accident	Jln Jeruju, Singapore
Additional Location Information	ALONG JALAN JERUJU
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCW8675T

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	PAULINE YAP
NRIC No	SXXXX668I
Email Address	tcspy78@yahoo.com.sg
Mobile Phone No	(Phone) +65-97647251
Alternative Phone No	(Home) +65-97647251

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Civic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	ThirdParty
Fleet Policy	No
Policy Number	DMPCSNW00081142100
Cover Note Number	-

DRIVER

Name of Driver	TAN CHOON SIONG

SKETCH PLAN #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Saturday around 6pm, I turned from Sembawang Road into Jalan Jeruju, I slowed down due to Pedestrian crossing the road. Suddenly, car B banged onto the rear of my car (car A) with loud bang. My travelling speed is ard 20Km/hr.

No Injury was reported.

DECLARATION

/We ... the foregoing particulars are true / every respect

DING AUTO PTE LTD
UEN No. 201311788Z