

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 10/12/2021

TP Veh Reg No: SML277B

Estimate No: ES2191203/AMK

Date: 14 Dec 2021

Policy No: D21MTPV01009671

Veh Reg No: SKH463A

Make/Model: TOYOTA TOYOTA
LEXUS RX270 AUTO

Chassis No: JTJZA11A302402243

Engine No: 1AR0457959

Reg. Date: 16/02/2011

Estimate Repair Cost to Vehicle No :SKH463A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	1,007.10	1 PC	1,007.10	✓
2 FRONT BUMPER SPONGE	153.40	1 PC	DAM 153.40	✓
3 FRONT BUMPER REINFORCEMENT	812.70	1 PC	R 812.70	X
4 FRONT BUMPER RH FOG LAMP COVER	72.90	1 PC	R 72.90	X
5 FRONT BUMPER RH SIDE RETAINER	138.00	1 PC	Diy 138.00	✓
6 FRONT BUMPER NUMBER PLATE GARNISH	164.80	1 PC	CMS 164.80	✓
7 FRONT BUMPER CLIPS	4.50	6 PCS	R 27.00	✓
8 FRONT GRILLE ASSY	934.90	1 PC	R 934.90	✓
9 FRONT GRILLE INNER TOP GARNISH	367.60	1 PC	R 367.60	X
10 RH HEADLAMP	2,723.40	1 PC	MCM 2,723.40	✓
11 REAR BUMPER	960.30	1 PC	R 960.30	✓
12 REAR BUMPER REINFORCEMENT	738.10	1 PC	R 738.10	✓
13 REAR BUMPER SPONGE	173.10	1 PC	CMS 173.10	✓
14 REAR BUMPER LH SIDE RETAINER	125.40	1 PC	Diy 125.40	✓
15 REAR BUMPER LH CORNAL RETAINER	100.70	1 PC	Diy 100.70	✓
16 REAR END PANEL	918.50	1 PC	R 918.50	X
17 TAILGATE LOGO	85.80	1 PC	R 85.80	✓
18 TAILGATE EMBLEM (RX)	104.40	1 PC	R 104.40	✓
19 TAILGATE EMBLEM (LEXUS)	79.90	1 PC	R 79.90	✓
			9,688.00	
		Less 25%	2,422.00	7,266.00

Special Net

20 FRONT NUMBER PLATE	35.00	1 PC	R 35.00	✓
21 REAR END PANEL SEALANT	40.00	1 UNIT	R 40.00	X
22 PARKING SENSORS	280.00	4 PCS	1,120.00	✓
		1 Set	1,195.00	1,195.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department


WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 10/12/2021
TP Veh Reg No: SML277B

Estimate No: ES2191203/AMK
Date: 14 Dec 2021
Policy No: D21MTPV01009671
Veh Reg No: SKH463A
Make/Model: TOYOTA TOYOTA
LEXUS RX270 AUTO
Chassis No: JTJZA11A302402243
Engine No: 1AR0457959
Reg. Date: 16/02/2011

Estimate Repair Cost to Vehicle No :SKH463A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
23 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,HEADLAMP,KNOCK & REPAIR FRT PANEL AND REALIGN BONNET THE SAME	600.00	1 LA	600.00	300
24 PUTTY & RESPRAY FRT BUMPER,BONNET,FRT PANEL,FRT RH FENDER AND ALL AFFECTED AREAS	600.00	1 LA	600.00	400
25 REMOVE & REFIX REAR BUMPER & ATTACHMENT,CUT,WELD & RENEW REAR END PANEL,KNOCK & REPAIR REAR SPARE TYRE PANEL & REALIGN TAILGATE THE SAME	750.00	1 LA	750.00	450
26 PUTTY & RESPRAY REAR BUMPER AND PARKING SENSORS,TAILGATE,REAR END PANEL AND ALL AFFECTED AREAS	750.00	1 LA	750.00	600
27 RUSTPROOFING	60.00	1 LA	nn 60.00	X
			2,760.00	2,760.00
			Total	S\$ 11,221.00
			Add GST @ 7%	785.47
			Total Amount Payable	S\$ 12,006.47

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE