Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 14 Feb 2022

Preliminary Advice

Vehicle No	: SKF2836E	Accident Date	: 18/12/2021
Make	: AUDI Q3 SPORTBACK	Policy No.	: 7210086538
Assignment Date	: 22/12/2021	Excess	: S$0.00
Date of Inspection	: 21/12/2021	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	21,249.00
Revised Amount	:S$	8,973.00
Check Items (Estimated)	:S$	1,939.00
Total	:S$	10,912.00
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	185,000.00
COE / PARF Rebate	:S$	79,078.00
Salvage Value	:S$	

Margin for Repair :S$ 105,922.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : KINDLY APPROVE ON CHECK ITEMS.