PRS Filed By: GQ REF: CS3/ASM21013068/Gvy3

PRS

# ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s LIAN CHIN HENG

of

Insured: SH 7625J

Policy No.

Claims No. S1M03MX3

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.




Bal. or Market Value: RM 5000

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: JPA 4540 Yr Regn: 2012 /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA 135LC c.c 135

Colour RED A/C: Insured / Std / NI / NA

Sp.Reading 45568 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PMYKG0540C0090910 *

Gen. Cond Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90-17

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or MAXXIS

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 4 mm | R/Bal. | 4 mm |
| L/Bal. | mm | L/Bal. | mm |

D.O.A. 24/11/21 D.O.I. 23-12-2021

Survey held at W/S 5PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | $1000 - $2000 |
| 12/1/22 | Submit PRS, repair range $1,000-$2,000 |

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 12/1/22-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($ )

☐ : Interview ($ )

☐ : Tech. Invs ($ )

☐ : Weekend ($ )

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL

Report Format:

Lump Sum / UPD: