


Section A - Accident Details

Registration Number	SHB5558U
Case Reference Number	TAX/01/22/2003
Registration Date	30/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHOO KWAI SING
Type of Accident	Side Swipe
Accident Date and Time	1/1/2022 4:50 PM
Accident Reported Date and Time	3/1/2022 10:05 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113556
Special Instruction to ARC, if any	TP / REAR PORTION
Prepared Date and Time	3/1/2022 4:16 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$807.00	\$400.00
Total Spray Cost	\$936.00	\$300.00
Total Spare Part Cost	\$2,895.52	\$1,191.29
Total Other Cost	\$550.00	\$70.00
TOTAL COST	\$5,188.52	\$1,961.29
Lump Sum Total	\$5,200.00	\$1,950.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	GUO QIANG (LKK) / AIG
ARC / Surveyor Sign Off Date	06/01/2022 4:35 PM	06/01/2022 4:32 PM
Signature		
Remarks	Total number of repair days = 3 days. SUP = + 1 day.	LUMP SUM REPAIR / AFTER PAINT PHOTO .

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/03/2022

User ID PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2201-0180	Invoice Number	
Quotation Date	17.01.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00 ✓
TO REPAIR REAR END PANEL	\$300.00	\$200.00 ✓ SUPP
Total Labour	\$807.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY BUMPER BEAM	\$378.00	\$0.00 X NN
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY REAR PANEL	\$180.00	\$100.00 ✓ SUPP
Total Spray Painting & Panel Beating	\$936.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK & RESET SYSTEM FUNCTION	\$150.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$40.00	\$0.00 NN
ADDITIONAL TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$0.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 X NN
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00 X NN
Total Other Costs	\$550.00	\$70.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5839947030	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given
		5839847050	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Check
		8149747020	COVER, REAR COMBINATION LAMP, RH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Check
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given

X
X
X NN
X
X
X
✓
✓
✓
X
X
NN

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/03/2022

User ID PohSuan

		52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		52592470 40	SEAL, RR BUMPER , LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		52591470 50	SEAL, RR BUMPER , RH	0.00	\$85.20	0.00	\$0.00	Replace	Check
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		64718470 80C0	END PANEL , COVER, DECK TRIM SERVICE HOLE	0.00	\$47.00	0.00	\$0.00	Replace	Not Given
		64716471 30C0	END PANEL , COVER, DECK TRIM, REAR	0.00	\$122.80	0.00	\$0.00	Replace	Not Given
		81581470 10	LENS & BODY ASSY , RR BUMPER , RH	1.00	\$486.80	10.00	\$438.12	Replace	Replace
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
Total					\$3,860.80		\$1,219.18		

✓ { MEC
✓
X { NV
X
X
✓ Re
X { NV
X
✓ CRA
X NV
✓ Cut

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52565479 00	FILLER, RR BUMPER , RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given
Total					618.70		269.93		

✓✓ CRA
✓✓ BR
X NN

1,489.11
-20%
1191.29 L/S \$1,950/-
400.00
370.00
1,961.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: