ASS. REC. BY: Kenneth

REF: CTZ/22000307/K — Kny3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Thiam Heng Hong

of

Insured: 218X

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 70 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SLM 8124 Yr Regn: 03.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic c.c 1597

Colour M.P. white A/C: Insured / Std / Nil / NA

Sp.Reading 126553 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: MRHFC5850GT001108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inordar / Jammed / Leaked / Burnt or

Brake: Inordar / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm
D.O.A.	5/1/22	D.O.I.	11/1/2022

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	Est not ready
	Kenneth confirmed lump sum: $ 2200 and 4 days
	(red, $4644.2, 68%)

Date, File Pass to? 20/01/23

☐ : Prell. Report

☐ : Final Report

Date, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ Tech Invs ($)

☐ Weekend ($)

Format : tp

Sum / I.B.I: ($ 2200

Survey Fee:

Transportation: $ + RS $

Parts

Others

TOTAL

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: admin@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior consent of Lim Tan Motor Pte Ltd