

威利摩哆

WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

*Not Authored
1/1000 82000-
Preserving After Paint
4 days*

10-JAN-2022

CHINA TAIPING Co (S) PL
105 Cecil Street
#18-00 The Octagon
Singapore 069534

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SFG605Y

Accident involving vehicle no: SML9733S/SFG605Y

DOA: 06/01/2022 at NICOLL HIGHWAY TOWARDS KPE BEFORE KPE

Dear officer in charge

Estimate cost of repair for vehicle no: SML9733S

To supplied:

Description	Qty	Amount
Lid	1	R 655.80 X
Lid – Corolla emblem	1	mc 42.35 —
Lid – Altis emblem	1	mc 44.17 —
Lid – Toyota logo	1	mc 50.25 —
Lid handle	1	su 298.20 X
Lid lock	1	R 382.00 X
Lid reflector	2	su 590.40 X
Lid hinge	2	R 184.00 X
Boot weatherstrip	1	mc 166.40 506m ✓
End panel	1	R 581.20 X
End panel top garnish	1	mc 229.40 ✓
Rear bumper	1	mc 482.00 ✓
Rear bumper sponge	1	su 75.20 X
Rear bumper retainer	1	mc 92.33 ✓
Rear bumper reflector	2	su 113.80 X
Rear bumper enforcement	1	mc 301.60 ✓
Tailamp <i>also</i>	2	mc 603.20 L+
Parts		4,892.30
Parts less 25%		3,669.23

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Reverse sensor
 To remove damaged parts & attachments
 Weld and cut damaged panel
 Repair/reshape dented areas
 Straighten rear chassis when necessary
 Replace/align all parts into position
 To spray paint

DU 220.00 *2005AL*

1100.00 *430L*
 1200.00 *600L*

 6,189.23

OK