REC'D / Rec'd By: GQ | REF: NS/INC22000570/Gqc

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s SMRT

of

Insured:

Policy No.

Claims No. MT/1165878-001

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMB3616P Yr Regn: 01 Dec 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: ALEXANDER DENNIS ENVIRO500 c.c 8849

Colour MULTICOLOER A/C: Insured / Std / NI / NA

Sp.Reading 420055.8 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SFD76CLR5FMTL4098 *

Gen. Cond Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 305/70R22.5

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FIRENZA

Front		Rear	
R/Bal.	6 mm	R/Bal.	6/6 mm
L/Bal.	6 mm	L/Bal.	6/6 mm
D.O.A.		D.O.I.	14-01-2022

Survey held at W/S 4:30

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	GIA give later
	~~We will be advising our Principal a cost of repair of $1068 before GST/- with~~ 2 days of repair, subject to their approval. (Red $2138.25, 67%)

Date/Time, File Pass to? 1) 22/03 Typist

Date/Time, File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weeend ($)

Report Format : TP

Labour / UPD : 1068

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL