





ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 130122

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 13.01.2022

Cheah Geok Tseng (Xie Yuzhen)

50 Cedar Avenue

Singapore 349718.

Volkswagen Sharan 2.0 TSi

Estimate Repair Cost for Vehicle Reg. No: SJR 663 Z

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 Pc. Rear Boot	HH		4,390.00	X
1 Pc. Sharan Emblem	HH		98.00	X
1 Pc. 2.0 TSi Emblem	HH		90.00	X
1 Pc. Rear Bumper	Distorted / Rebuilt		1,690.00	✓ 1378.97
2 Pcs. Rear Bumper Side Retainer	SVL	@ 109.00	218.00	X
1 Pc. Rear Bumper Centre Retainer Bracket	Sw broken		230.00	✓
1 Pc. Rear Bumper Sponge	NF		192.00	X
1 Pc. Rear Bumper Reinforcement with Hook	Deform		1,990.00	✓ 865.80
1 Pc. Rear Bumper Lower Spoiler	distorted		478.00	✓ 328.35
4 Pcs. Rear Lower Spoiler Clips	HH	@ 20.00	80.00	✓ 15/- SH
2 Pcs. Rear Bumper Reflector	HH	@ 92.00	184.00	X
10 Pcs. Rear Bumper Clips	HH	@ 8.00	80.00	20/- SH
1 Pc. Rear Exhaust	HH		1,590.00	X
1 Pc. Rear Exhaust Heat Shield	SVL		398.00	X
2 Pcs. Exhaust Hanger	HH	@ 58.00	116.00	X
1 Pc. Exhaust Bracket	HH		86.00	X
1 Pc. Rear End Panel	HH		268.00	X
1 Pc. Rear End Panel Garnish Inner Trim	HH		499.00	X
1 Pc. Rear Inner End Panel	HH		298.00	X
1 Pc. Rear Windscreen Moulding	HH		298.00	X
1 Set. Rear Windscreen Repair Kit & Sealant	HH		180.00	X
1 Pc. Rear Windscreen Seal	HH		60.00	X
4 Pcs. Parking Sensor 2pc Dam 2pc HH		@ 298.00	1,192.00	✓ 596.00
4 Pcs. Parking Sensor Seal 2pc HH 2pc HH		@ 38.00 4.50	152.00	✓ 9.00
4 Pcs. Parking Sensor Holder	SVL	@ 59.00	236.00	X
1 Pc. Parking Sensor Wire	HH		399.00	X
1 Pc. Towing Hook cover	White		189.00	✓
Total (Panels / Parts):			15,492.00	(SGD)

List 3597.12

SH 35.00 =

10% 3237.40




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit wiring & check.

~~180.00~~ 30/-

To repair & refit interior garnish, sideboard & all
Accident affected area.

280.00 HH

To remove & refit rear windscreen.

180.00 HH

To remove & refit rear exhaust muffler.

930.00

280.00 HH

To knocking, welding, straightening & all accident
Affected damaged area.

~~1,000.00~~ 600/-

To respray painting on all accident inner & outer
accident affected area.

~~900.00~~ 300/-

To rust proof all accident affected area.

~~150.00~~ HH

Total (Labor Charges): 2,970.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS
LABOR CHARGES

18/01/2022 @ 1000m

WAT Antenna

2/5mm

4 days.

15,492.00 L/S

2,970.00

4202.40

3,300/-

Grand Total:

18,462.00 (SGD)

[Signature] LKK And *[Signature]*

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.