# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD	Ref:	CS3/ASM22001435/Evy3e2
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811	Date:	18/02/2022
ATTN: TEO KITTY	Code:	ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGT 61K	Veh. Inspected	SLN 2328B
Policy No.		Coverage ($)	0.00
Claim No.	S2M03T75	Excess ($)	0.00
Assign From	TEO KITTY	Assign Date	15/02/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH104560672	Colour	RED
Odometer	190362 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	BRIDGESTONE	5 mm
L/H Front Tyre	215/45 R17	BRIDGESTONE	5 mm
R/H Rear Tyre	215/45 R17	BRIDGESTONE	5 mm
L/H Rear Tyre	215/45 R17	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

5. General Information

Accident Date	11/02/2022	Inspect Date / Time	15/02/2022 (02:15 PM)
Survey held at	V-TECH AUTO SERVICE		
	No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $5,000-$6,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	**7 Working Days**

Report Ref No. CS3/ASM22001435/Evy3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser