

SME MOTOR PTE LTD

Unit 6, #02-15@ Kaki Bukit, Singapore 417883

Tel: 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST:201119451E RCB NO:201119451E

National Insurance Pte Ltd

Claim No :

No :

Date :

12/02/2022

Policy No :

P10519276R00

Veh Reg No :

SMH9786K

Make / Model :

Honda Civic

Chasis No :

Engine No :

Reg. No :

FAX:

Motor Claim Department

No : 22/III/TP-030 (02)

Type : TP CLAIM

Report Date : 09/02/2022

ESTIMATE FOR VEHICLE NO: SMH9786K

Discription	Quantity	List Price	Amount
Cost Price			
1 REAR BONNET	1 PC	\$350.00	\$350.00
2 REAR BONNET HINGE	2PCS	\$110.00	\$110.00
3 REAR BOOT LOCK	1 PC	\$75.00	\$75.00
4 REAR BOOT OUTER GARNISH	1 PC	\$105.00	\$105.00
5 REAR BOOT CENTER LOGO	1 PC	\$25.00	\$25.00
6 REAR BOOT 'CIVIC' EMBLEM	1 PC	\$25.00	\$25.00
7 REAR BOOT 'i-VTEC' EMBLEM	1 PC	\$30.00	\$30.00
8 REAR BOOT LAMP	2PCS	\$240.00	\$240.00
9 REAR TAIL LAMP	2PCS	\$390.00	\$390.00
10 REAR BUMPER	1 PC	\$260.00	\$260.00
11 REAR BUMPER RETAINER	2PCS	\$30.00	\$30.00
12 REAR BUMPER CLIP	10PCS	\$20.00	\$20.00
13 REAR BUMPER SIDE TRIM	2PCS	\$36.00	\$36.00
14 REAR BUMPER LOWER SPOILER	1 PC	\$50.00	\$50.00
15 REAR BUMPER REINFORCEMENT	1 PC	\$150.00	\$150.00
16 REAR BOOT INNER RUBBER	1 PC	\$55.00	\$55.00
17 REAR END PANEL	1 PC	\$260.00	\$260.00
18 REVERSE SENSOR	2PCS	\$190.00	\$190.00
19 REAR END PANEL TOP GARNISH	1 PC	\$45.00	\$45.00
20 REAR END PANEL TOP GARNISH CLIP	6PCS	\$18.00	\$18.00
21 REAR TAIL LAMP PANEL	2PCS	\$130.00	\$130.00
22 REAR SPARE TYRE FLOOR PANEL (NO STOCK)	1 PC	\$480.00	\$480.00
23 REAR SPARE TYRE BOARD COVER	1 PC	\$80.00	\$80.00
24 REAR LH CHASSIS (NO STOCK)	1 PC	\$550.00	\$550.00
25 REAR LH FENDER	1 PC	\$620.00	\$620.00
26 REAR WINDSCREEN MOULDING	1 PC	\$120.00	\$120.00
27 REAR LH FENDER GLASS MOULDING	1 PC	\$145.00	\$145.00
28 REAR PETROL TANK COVER RIVERT	4PCS	\$20.00	\$20.00
29 FRT BONNET	1 PC	\$430.00	\$430.00
30 FRT BONNET HINGE	2PCS	\$110.00	\$110.00
31 FRT BONNET LOCK	1 PC	\$95.00	\$95.00
32 FRT GRILLE	1 PC	\$90.00	\$90.00
33 FRT GRILLE OUTER MOULDING	1 PC	\$105.00	\$105.00
34 FRT GRILLE CENTER LOGO	1 PC	\$25.00	\$25.00
35 FRT GRILLE CLIP	4PCS	\$8.00	\$8.00
36 FRT BUMPER	1 PC	\$260.00	\$260.00
37 FRT BUMPER RETAINER	2PCS	\$36.00	\$36.00
38 FRT BUMPER CLIP	10PCS	\$20.00	\$20.00
39 FRT BUMPER TOP RUBBER SEAL	1 PC	\$35.00	\$35.00
40 FRT BUMPER LOWER GRILLE	1 PC	\$50.00	\$50.00
41 FRT BUMPER BEAM (BELOW HEADLAMP)	2PCS	\$50.00	\$50.00
42 FRT BUMPER REINFORCEMENT	1 PC	\$295.00	\$295.00
43 HEADLAMP (NO STOCK)	2PCS	\$1,900.00	\$1,900.00
44 HEADLAMP SUPPORT PANEL	1 PC	\$450.00	\$450.00
45 HEADLAMP SUPPORT TOP GARNISH	1 PC	\$40.00	\$40.00
46 SUPPORT TOP GARNISH CLIP	8PCS	\$16.00	\$16.00
47 AIRCON CONDENSER	1 PC	\$450.00	\$450.00
48 RADIATOR	1 PC	\$460.00	\$460.00
49 RADIATOR MOTOR	1 PC	\$260.00	\$260.00
50 RADIATOR MOTOR COWLING	1 PC	\$85.00	\$85.00
51 RADIATOR FAN BLADE	1 PC	\$55.00	\$55.00
52 FRT BUMPER CENTER TOP BEAM	1 PC	\$125.00	\$125.00
53 AIRCON SIDE DEFLECTOR	2PCS	\$110.00	\$110.00
54 FRT BUMPER FOG LAMP GARNISH	2PCS	\$90.00	\$90.00
55 HEADLAMP CHROME	2PCS	\$190.00	\$190.00
56 FRT FENDER	2PCS	\$440.00	\$440.00
57 WIPER CORNER GARNISH	2PCS	\$50.00	\$50.00

Plus 10%

\$10,939.00

\$1,093.90

\$12,032.90

Not Authorized
here
15/2/22

P/P #16332.50
Warranty Behn pely.
including 2 wts.
18 days.

9510

CROSSMEMBER PLATE
WINDSCREEN GUM
REAR LH FENDER GLASS GUM
NUMBER PLATE
RADIATOR COOLANT
REAR FLOOR PANEL SEALANT

1 PC *3m*
1 PC *per*
1 PC *per*
1 PC *3m*
1 PC *per*
1 PC *na*

\$40.00 ✓
\$60.00 *40*
\$50.00 *30*
\$40.00 ✓
\$25.00 ✓
\$60.00 *50*
\$275.00

Labour

- 1 WIRE CHECKING
- 2 REMOVE & REFIX REAR WINDSCREEN
- 3 REMOVE & REFIX REAR LH FENDER GLASS
- 4 REMOVE & REFIX CUSHION AND SEATS
- 5 REMOVE & REFIX PETROL TANK
- 6 REMOVE & REFIX REAR UNDERCARRIAGE (WITH CROSSMEMBER)
- 7 4 WHEEL ALIGNMENT
- 8 REMOVE & REFIX CUSHION AND SEATS
- 9 LABOUR CHARGE
- 10 SPRAY PAINTING

\$30.00 ✓
\$120.00 ✓
\$60.00 ✓
\$180.00 *100*
\$180.00 *60*
17 \$350.00 *X*
17 \$80.00 *X*
payable \$100.00 *X*
\$3,000.00 *2800*
\$2,400.00 *1900*
\$6,500.00

Amount Before Excess	\$18,807.90
Less Excess	\$0.00
Amount Before GST	\$18,807.90
Add GST @7%	\$1,316.55
Total Amount Payable	\$20,124.45

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE

P-9925
+ 10%
P-10917.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S.N-225
L-5190
16332.50

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

IA International Insurance Pte Ltd

4 Cecil Street # 04-05

IOB Building

Singapore 049711

FAX:

Motor Claim Department

Ref No : 22/III/TP-030(02)

Claim Type : Third Party

Accident Date : 09/02/2022

TP Veh Reg No : SMN2983Y

ESTIMATE

Tax Invoice No : SUPPLEMENTARY

Date : 16/03/2022

Policy No : P10519276R00

Veh Reg No : SMH9786K

Make / Model : HONDA CIVIC

Chasis No : 0

Engine No:

Reg. No :

Discription	Quantity	List Price	Amount
Cost Price			S\$ S\$
1 AIR CLEANER BOX LOWER <i>one</i>	1 PC		\$95.00
2 AMBIENCE SENSOR BRACKET <i>changed</i>	1 PC		\$10.00
3 REAR FLOOR PANEL SIDE JOINT <i>BUC</i>	2 PCS	\$75.00	\$150.00
4 REAR END PANEL SIDE JOINT <i>3 surf</i>	2 PCS	\$45.00	\$90.00
5 REAR ALARM BUZZER <i>one</i>	1 PC		\$70.00
			\$415.00
	10.00%		\$41.50
			\$456.50

LABOUR:

1 REMOVE & REFIX EXHAUST

TOTAL

120

~~\$250.00~~

\$250.00

Amount Before Excess	\$706.50
Add GST @7%	\$49.46
Total Amount Payable	\$755.96

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE