



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203640

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 13/06/2022
Reference CC6/CTI22001829/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 1252Z
Insured Veh. GBF 208M
Claim No. SNM22D201330/C02
Policy No. DMCVSNW00039972100
Accident Date 23/02/2022
Inspection Date 25/02/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22001829/Uea3q2 Date: 13/06/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 208M	Veh. Inspected	SMA 1252Z	
Policy No.	DMCVSNW00039972100	Coverage (\$)	0.00	
Claim No.	SNM22D201330/C02	Excess (\$)	0.00	
Assign From		Assign Date	25/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI (A)	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFEAJ11U1486651	Colour	WHITE	
Odometer	116572 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	GOODYEAR	6 mm	
L/H Front Tyre	215/60 R17	GOODYEAR	6 mm	
R/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/02/2022	Inspection Date	25/02/2022	
Survey held at	SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 1252Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAIL GATE (N)	TO REPAIR SEE LABOUR	3,368.90	-
1	TAIL GATE EMBLEM (N)	NOT NECESSARY	64.90	-
1	TAIL GATE RUBBER (N)	NOT NECESSARY	209.00	-
1	TAIL GATE QASHOAI PLATE (N)	NOT NECESSARY	94.40	-
2	TAIL GATE DAMPERS @\$250.00 (N)	NOT NECESSARY	500.00	-
1	TAIL GATE TOP LOCK (N)	NOT NECESSARY	190.50	-
1	TAIL GATE LOWER LOCK (N)	NOT NECESSARY	34.80	-
1	TAIL GATE WINDSCREEN OUTER RUBBER LOWER (N)	NOT NECESSARY	95.00	-
2	TAIL GATE WINDSCREEN TOP SIDE RUBBER @\$25.00 (N)	NOT NECESSARY	50.00	-
1	REAR BUMPER (N)	DEFORMED	876.40	796.70
1	REAR BUMPER INNER SPONGE (N)	TORN	155.60	126.40
2	REAR BUMPER REFLECTOR @\$61.90 (N)	CRACKED	123.80	123.80
1	REAR BUMPER REINFORCEMENT (N)	BENT	691.50	619.20
2	REAR BUMPER REINFORCEMENT HOLDERS @\$141.00 (N)	DENTED	282.00	252.00
4	REAR BUMPER LOWER BRACKETS @\$35.70 (N)	NO SUCH PARTS	142.80	-
1	SET REAR BUMPER INNER CLIPS (N)	NECESSARY	50.00	30.00
2	REAR BUMPER SIDE HOLDERS @\$39.90 (N)	NOT NECESSARY	79.80	-
1	REAR PANEL (N)	TO REPAIR SEE LABOUR	482.60	-
1	REAR PANEL LOWER LOCK COVER (N)	NOT NECESSARY	258.00	-
2	TAIL LAMPS @\$346.90 (N)	N/S CRACKED	693.80	323.70
2	REAR FENDER OUTER COVERS @\$540.50 (N)	TORN	1,081.00	962.00
1	TOW COVER (N)	DEFORMED	21.20	21.20
	LESS 5% DISCOUNT		-477.30	-
	LESS 10% DISCOUNT		-	-325.50
			9,068.70	2,929.50
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	1,120.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN INNER SEALANT (SN)	NECESSARY	140.00	40.00
			1,260.00	240.00
	LABOUR			
	TO RUSTPROOF.	NOT NECESSARY	200.00	-
	TO REMOVE/REFIT REAR TOP SPOILER/	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE /RENEW TAIL GATE .	NOT NECESSARY	150.00	-
	TO DISMANTLE /RENEW REVERSE SENSORS.		100.00	50.00
	TO REMOVE/REFIT REAR WINDSCREEN.	NOT NECESSARY	140.00	-
	TO REMOVE/REFIT REAR INTERIOR TO EFFECT REPAIR.		150.00	60.00
	TO DISMANTLE /RENEW ACCIDENT PORTION .INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR PANEL .		1,500.00	580.00
	TO SPRAY PAINT.		1,500.00	800.00
GRAND TOTAL			14,298.70	4,679.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CC6/CTI22001829/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 1252Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 1252Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 1252Z

RE-INSPECTION

