AIS Filed By: GQ | Ref: AISCS6/AIS22002063/Gny3

ASSIGNMENT

From: Date:

Estimated Cost:

[OD] / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s MOVA AUTO

of

Insured:

Policy No.

Claims No. 2022 22004114FR

Sum Insured: Excess: TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $74k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / [REV] / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SML5183E Yr Regn: 24 May 2019

Type [M.Car] M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA VIOS c.c 1496

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 44544 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR2B23F3201174483

Gen. Cond [Good] / Fair / Poor / Burnt

Steering: [Inorder] / Jammed / Leaked / Burnt or

Brake: [Inorder] / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / [STD A/Rim] or

Tyre Size: F: —

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or —

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	07-03-2022

Survey held at OFFICE 4PM

Des. of Damages : [Frt] / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	We will be advising our Principal a cost of repair at Part-by-Part $ 4,655.40 & 7 working days, subject to their approval.
	(red, 289.50, 6%)

Date/Time, File Pass to? [ ] : Preli. Report

1) 11/11/22 [ ] : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: [ ] : Site Insp ($)

[ ] : Interview ($)

[ ] : Tech. Invs ($)

[ ] : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL

Report Format:

Lump Sum / UPR: 4655.40