

cecilia

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC INSURANCE PTE LTD

78, Shenton Way #07-16 AIG Building

S,pore 079120

Accident date:07/03/2022

Date:08/03/2022

not Arthur
del
8/3/22
4/5 @ 6250/
8 days.

Estimate cost to repair vel: SLN 6244H (Mazda 2) claims under vel: SNC 9504Y.

1pce boot lid	\$ 861.80	Body ID ✓	
2pcs boot lid <u>hinges@\$115.50</u>	231.00	R X	
1pce boot lid emblem	58.80	del ✓	
1pce boot lid skyactiv plate	67.60	del ✓	
1pce boot lid mazda palte	57.90	del ✓	
1pce boot lid top lock	190.90	del ✓	
1pce boot lid lower lock	35.10	17 X	
1pce boot lid lock switch	209.20	Che ✓	
1pce boot lid rubber	112.90	twi ✓	
2pcs boot lid <u>reflectors@\$208.20</u> 190x2=380	416.40	Che ✓	
1pce boot lid insulator	302.60	del/torn ✓	
2pcs tail <u>lamps@\$395.30</u>	790.60	Che ✓	
2pcs tail lamp inner <u>panels@\$287.70</u> 250x2=500	575.40	del ✓	
6pcs tail lamps inner clips@\$8	48.00	17 X	
1pce rear panel ^{inner}	656.00	Body ID ✓	600.50
1pce rear panel lower lock cover	210.70	twi ✓	
2pcs rear fenders inner trim covers@\$282.50	565.00	del/twi ✓	
1pce rear exhaust pipe	1,026.80	R X	
1pce rear exhaust pipe outer chrome	180.00	del X	
2pcs rear exhaust pipe rubber holders@\$45	90.00	del X	
1pce rear bumper 945	954.50	dis ✓	
1set rear bumper reverse sensors	400.00	shock 200 S/N	
2pcs rear bumper reflectors@\$53	106.00	Che ✓	
2pcs rear bumper top side clips@\$10	20.00	del X	
2pcs rear bumper side <u>holders@\$45.80</u>	91.60	del ✓	
10pcs rear bumper inner clips@\$8	80.00	del 50	
1pce rear bumper reinforcement	198.20	NF X	
2pcs rear bumper inner <u>brackets@\$68.40</u>	136.80	page1 NF X	

1set

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC INSURANCE PTE LTD

78, Shenton Way #07-16 AIG Building

S,pore 079120

Accident date:07/03/2022

Date:08/03/2022

Estimate cost to repair vel: SLN 6244H (Mazda 2) claims under vel: SNC 9504Y.

[illegible]

- LK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-6 622-50
 202
25298
 S.N-200
 L-2330
7828
 6262