PRS Filed By: GQ REF: CS3/SMR21012734/Gvy3-1

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Motor 51

of

Insured: SHD 6273Z

Policy No.

Claims No. TAX/11/21/2060

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: $

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBQ8869U Yr Regn: 2 JAN / 2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA / MX KING T150 c.c 150

Colour BLUE A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MH3UG0750KK 043659

Gen. Cond Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90-17

R: 90/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 26/11/21 D.O.I. 20-12-2021

Survey held at W/S 11:15

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$1000 - $2000
	GIA give later
28/12/21	Submit PRS, repair range $1000-$2000
18/3/22	Submit LS $350 (Red 1650, 82%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 18/3/22-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format:

Lump Sum / LPO:

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL