ASS. REC. BY: Kenneth

REF: CTL / 22002383 / KT

Kny3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Cartimes

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of Inspection.

N/S	O/S

Bal. or Market Value: $8K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 ~~10~~ days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMF 134L Yr Regn: 10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Vezel c.c 1496

Colour M. Black A/C: Insured / Std / NI / NA

Sp.Reading 72385 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU1 · 1302990

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F Firenza 215/60R16

R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	8 mm	R/Bal.	5 mm
L/Bal.	8 mm	L/Bal.	5 mm
D.O.A.	11/3/12	D.O.I.	15/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	

final fig : $13,862.95 and 12 days

~~(red: 897.05, 0.60%)~~

(red: $4401.05, 24%)

Date/Time, File Pass to?

1) 05/08/22

Date/Time, File Return to?

2)

☐ : Prell. Report

☐ : Final Report

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ Tech Invs ($)

☐ Weekend ($)

Survey Fee:

Transportation: S + RS S

Others

TOTAL

Report Format : tp-merimen

Lump Sum / I.B.I: ($ 13,862.95)