# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD	Ref:	CS3/ASM22002442/Rqy3e2
8 SHENTON WAY #24-01	Date:	29/03/2022
AXA TOWERSINGAPORE 068811		
ATTN: OH VALE	Code:	ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLL 600M	Veh. Inspected	SLV 7075E
Policy No.	P1891271	Coverage ($)	0.00
Claim No.	S2M03VDS	Excess ($)	0.00
Assign From	OH VALE	Assign Date	16/03/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ 1.5 CVT	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMGK5850JX201940	Colour	WHITE
Odometer	45411 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

5. General Information

Accident Date	09/03/2022	Inspect Date / Time	16/03/2022 (05:20 PM)
Survey held at	14 ANG MO KIO St. 63 BLK B SINGAPORE 569116		
Repairer	ASSURE AUTO ASSIST PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,000-$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	**6 Working Days**

Report Ref No. CS3/ASM22002442/Rqy3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser