

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

18/3/22
10am

SURVEYOR COPY

M/S : REVATHY D/O V SINNAIAH
BLK 314 HOUGANG AVE 5 #12-131

SINGAPORE 530314

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 13/03/2022
TP Veh Reg No: SNC2088C

Estimate No: MC1902533
Date: 14 Mar 2022
Policy No: MT/00990343
Veh Reg No: SKR5368G
Make/Model: TOYOTA COROLLA
ALTIS 1.6L CVT

Not Notified

Repairing

2 days

81087.55

Estimate Repair Cost to Vehicle No :SKR5368G

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR BOOT EMBLEM	1 PC	<i>na</i> 50.70 <i>X</i>	
2 REAR BOOT LOGO "COROLLA"	1 PC	<i>na</i> 49.10 <i>X</i>	
3 REAR BOOT LOGO "ALTIS"	1 PC	<i>na</i> 49.10 <i>X</i>	
4 REAR BOOT RUBBER	1 PC	<i>ln</i> 175.80 <i>X</i>	
5 REAR BOOT LOCK	1 PC	<i>n</i> 399.50 <i>X</i>	
6 REAR BOOT LOCK CATCH	1 PC	<i>n</i> 15.30 <i>X</i>	
7 REAR BUMPER	1 PC	<i>Bu</i> 556.40 <i>✓</i>	
8 REAR BUMPER UPPER RETAINER LH & RH	2 PC	<i>ln</i> 218.60 <i>X</i>	
9 REAR BUMPER SIDE RETAINER LH & RH	2 PC	<i>ln</i> 120.80 <i>X</i>	
10 REAR BUMPER CLIPS	6 PC	<i>na</i> 27.00 <i>✓</i>	
11 REAR BUMPER REINFORCEMENT	1 PC	<i>n</i> 399.50 <i>X</i>	
12 REAR BUMPER REINFORCEMENT ARM LH & RH	2 PC	<i>n</i> 136.40 <i>X</i>	
13 REAR END PANEL GARNISH	1 PC	<i>ln</i> 241.90 <i>X</i>	
14 REAR END PANEL GARNISH CLIP	2 PC	<i>na</i> 7.40 <i>X</i>	
		2,447.50	
	Less 25%	611.88	1,835.63
Special Nett			
15 REVERSE SENSOR SET	1 PC	<i>shay</i> 200.00 <i>✓</i>	
16 NUMBER PLATE	1 PC	<i>ln</i> 35.00 <i>X</i>	
		235.00	235.00
LABOUR			
17 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	60.00 <i>50l</i>	
18 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	<i>na</i> 60.00 <i>X</i>	
19 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR BOOT, REAR END PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00 <i>200l</i>	
20 TO SPRAY BOOT, REAR BUMPER, REAR END PANEL	1 PC	600.00 <i>200l</i>	
		1,320.00	1,320.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : REVATHY D/O V SINNAIAH
BLK 314 HOUGANG AVE 5 #12-131

SINGAPORE 530314

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 13/03/2022
TP Veh Reg No: SNC2088C

Estimate No: MC1902533
Date: 14 Mar 2022
Policy No: MT/00990343
Veh Reg No: SKR5368G
Make/Model: TOYOTA COROLLA
ALTIS 1.6L CVT

Estimate Repair Cost to Vehicle No :SKR5368G

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 3,390.63
		Add GST @ 7%	237.34
		Total Amount Payable	S\$ 3,627.97

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED TWENTY SEVEN AND CENTS NINETY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE