



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

not Authorized
21/3/22
2/5 #8200/
10 days.

21 March 2022

REG NO.: SML 5468 J
MAKE/MODEL: NISSAN SYLPHY

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

Nett

QTY	DESCRIPTION	AMT(S\$)
	NOT ITEMS	
1	Rear windscreen moulding 89.50	\$ Net 130.80
1	Rear boot lid 716.80	\$ Body 891.10
1	Rear boot chrome moulding 231.00	\$ Cne 323.10
2	Rear boot hinges 95.90	\$ v/s R 191.80 1pc
1	Rear boot inner trim	\$ warped 143.40
2	Rear boot lamps 161.40 x 2 = 322.80	\$ Cne 372.00
1	Rear boot lock	\$ Bert 91.80
1	Rear boot lock catch	\$ 11 47.50 X
1	Rear boot logo	\$ Net 43.80
1	Rear boot rubber	\$ Twi 74.20
1	Rear boot "SYLPHY" emblem	\$ Net 62.40
2	Rear taillamps	\$ Cne 832.00
2	Rear taillamp panels 205 x 2 = 410	\$ 205/Bert 983.60
1	Rear end panel	\$ Body 452.80
1	Rear end panel inner garnish 105.10	\$ Dis 161.30
1	Rear keyless sensor	\$ 11 185.50 X
1	Rear bumper 669.00	\$ Dis 784.40
2	Rear bumper brackets 91.70	\$ n/s 183.40 1pc
1	Rear bumper inner sponge	\$ Torn 84.60
2	Rear bumper reflectors 45.00	\$ n/s Cne 173.20 1pc
2	Rear bumper reflector covers 45.00	\$ NS 156.00 X
2	Rear bumper side retainers 35 x 2 = 70	\$ Bert/Twi 85.20
2	Rear number plate lamps	\$ 11 116.00 X
1	Rear floor board top board 488.60	\$ warped 566.00
1	Rear floor panel	\$ R 771.50 X
1	Rear exhaust silencer	\$ 11 486.40 X
2	Rear exhaust mountings	\$ 11 37.20 X
2	Rear fenders 1515.30	\$ v/s R 3,030.60 1pc
2	Rear fender air gates	\$ 11 104.60 X
2	Rear fender inner shields	\$ 11 69.00 X
2	Rear fender inner trims	\$ Re/Torn 778.00
		\$ 12,413.20
	Less 10%	\$ 1,241.32
		\$ 11,171.88

<u>SPECIAL NETT ITEMS</u>			
1	Rear windscreen sealant	\$ <i>neu</i>	80.00 <i>40</i>
1	Rear bumper clip (1 set)	\$ <i>neu</i>	45.00 <i>30</i>
1	Rear weekend seal	\$ <i>neu</i>	45.00 <i>18</i>
1	Rear weekend plate	\$ <i>neu</i>	50.00 <i>40</i>
1	Rear reverse sensor (1 set)	\$ <i>shotel</i>	350.00 <i>200</i>
1	Rear reverse camera	\$ <i>neu</i>	450.00 <i>X</i>
		\$	1,020.00

<u>S/N</u>	<u>LABOUR CHARGES</u>		
1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00 <i>30</i>
2	To remove and refit inner garnishes.	\$	150.00 <i>80</i>
3	To remove and refit rear reverse sensor and camera.	\$	150.00 <i>50</i>
4	To transfer boot lid mechanism and wiring assembly.	\$	80.00 <i>60</i>
5	To remove and refit fuel tank assembly with all attachments.	\$	150.00 <i>60</i>
6	To remove and refit rear windscreen glass.	\$	180.00 <i>120</i>
7	To remove, refit and replace exhaust silencer and mountings.	\$ <i>^ ^</i>	150.00 <i>X</i>
8	To apply undercoating.	\$	200.00 <i>100</i>
9	Panel beating.	\$	1,600.00 <i>1580</i>
10	To re-spray painting on the affected areas.	\$	1,500.00 <i>1200</i>
		\$	4,240.00

GRAND TOTAL :

\$ 16,431.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-7413.7
102
P-6672.33
S.N-328
L-3280
10280.33
202
8224