REF: CC4/GRB2200.2618/Dga³

ASSIGNMENT

COB March 2027

Veh No: SHC 2608 Z   **Yr Regn:** 2019/March

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

Truck / Trailer or

Make: Toyota Prius   c.c 1798

Colour: Blue   **A/C:** Insured / Std / NI / NA

Sp.Reading 402473   **T/Radio:** Insured / Std / NI / NA

Eng/No: 2ZR2B94683

C/No: JTDKB3FU803078796

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 195/65 R15
R: — 11 —

From: _____   **Date:** _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____   Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

	N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: Consistent? : Yes or **No**

GIA / PR Seen: Consistent? : Yes or **No**

Est. Repairs: 10 9 days   Res.: Yes or **No**

Lum Sum: 10% 20 %   3 Val.: Yes or **No**

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____   Person Contacted: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or   Westlake

Front		Rear	
R/Bal. 5'	mm	R/Bal. 5'	mm
L/Bal. 5'	mm	L/Bal. 5'	mm

D.O.A. 18/03/2022   **D.O.I.** 21/03/2022

Survey held at   Byfrost Sin Mine

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

H/o Prain

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time   Action / Instruction

III. SML 941 S

L/Sum at 10% cos no second hea hard parts. Repair change
most part.

02/09/22   finance d/s 15,300/- into 10 days of reg.