

cecilia

not Authorized
N/A

30/3/22

1/5 #10,300 /
6 days

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: SKU 2948L

1PC	FRONT BUMPER	De/torn	971.40	\$1,250.00	✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$65.00	n/s sent		\$130.00	12c
2PCS	FRONT BUMPER FOG LAMPS @\$305.00	n/s		\$610.00	X
2PCS	FRONT BUMPER FOG LAMP GARNISHS @\$160.00	n/s		\$320.00	X
1PC	FRONT BUMPER REINFORCEMENT	n/s		\$665.00	X
1SET	FRONT BUMPER CLIPS	n/s		\$50.00	✓
1PC	FRONT FENDER	body	350.60	\$545.00	✓
1PC	FRONT FENDER INNER SHIELD N/S	Torn	181.20	\$330.00	✓
1SET	FRONT FENDER INNER SHIELD CLIPS	n/s		\$50.00	✓
1PC	HEADLAMP N/S	scr/line	2295	\$5,360.00	✓
1PC	FRONT SUPPORT PANEL	n/s		\$541.00	X
1PC	WIPER WASHER TANK	n/s		\$281.00	X
1PC	FRONT SHOCK ABSORBER N/S	sent	360.80	\$1,136.00	✓
1PC	FRONT LOWER ARM N/S	sent	454.70	\$990.00	✓
1PC	FRONT KNUCKLE ARM N/S	sent	455.20	\$1,160.00	✓
1PC	FRONT KNUCKLE ARM BEARING N/S	Dye	250.00	\$700.00	✓
1PC	FRONT DRIVE SHAFT	n/s		\$1,400.00	X
1PC	FRONT DOOR MIRROR N/S	n/s		\$850.00	X
1PC	FRONT DOOR N/S	n/s		\$1,021.00	✓
1PC	FRONT DOOR FRAME BLACK GARNISH N/S	n/s		\$80.00	✓
1PC	FRONT DOOR INNER RUBBER N/S	n/s		\$112.00	✓
1PC	FRONT DOOR INNER LOCK N/S	n/s		\$455.10	X
1PC	FRONT DOOR INNER TRIM BOARD N/S	n/s		\$1,050.10	X
1PC	FRONT DOOR INNER GLASS REGULATOR N/S	n/s		\$399.00	X
1PC	REAR DOOR N/S	n/s		\$981.00	✓
1PC	REAR DOOR INNER RUBBER N/S	n/s		\$112.00	✓
1PC	REAR DOOR INNER LOCK N/S	n/s		\$455.10	X
1PC	REAR DOOR FRAME BLACK GARNISH N/S	n/s		\$80.00	✓
1PC	REAR DOOR HINGE N/S	n/s		\$66.00	X
1PC	REAR FENDER N/S	n/s		\$1,025.00	✓
1PC	REAR WINDSCREEN MOULDING	n/s		\$98.00	✓
1PC	REAR WHHEL HUB BEARING N/S	Dye	325.00	\$455.00	✓
1PC	REAR KNUCKLE ARM N/S	sent	422.50	\$545.20	✓
1PC	REAR TRAILING ARM N/S	sent	545.30	\$588.10	✓
1PC	REAR BUMPER	De/torn	981.20	\$1,250.00	✓
1PC	REAR BUMPER SIDE RETAINER N/S	n/s		\$65.00	✓
1SET	REAR BUMPER CLIPS	n/s		\$50.00	✓
1PC	REAR SPORT RIM N/S	waged		\$1,100.00	500 s/n
1PC	FRONT SPORT RIM N/S	waged		\$1,100.00	500 s/n
1SET	DOOR VISOR N/S	n/s		\$100.00	80 s/n
				\$27,555.60	

(20%)

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX ^{1/5} FRONT DOOR MECHANISM	\$120.00	100
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$250.00	120
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$250.00	120
TO CONDUCT WHEEL ALIGNMENT	\$120.00	80
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO RESET & REPROGRAMME SYSTEM	11 \$150.00	X
TO REFILL AIR CON GAS	11 \$120.00	X
TO SPRAY RUST PROOFING	\$120.00	✓
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,100.00	800
TO PUTTY & SPRAY PAINTING	\$2,200.00	1200
TOTAL	\$32,235.60	

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP 4A

Primary Colour: White

Manufacturing Year: 2015

Engine No: P520294469

Chassis No: JM5BN2ABG0312715

Maximum Power Output: 83.0 kW (112 bhp)

Open Market Value: 113,871.90

Original Registration Date: 16 Jun 2015

First Registration Date: 16 Jun 2015

Transfer Count: 15

Actual ARF Paid: \$19,314.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Jun 2022

PARF Rebate Amount: \$26,898.00

Intended COE Rebate Details

COE Expiry Date: 15 Jun 2022

COE Category: A

COE Period (Years): 10

QP Paid: \$58,700.00

COE Rebate Amount: \$19,314.00

Total Rebate Amount: \$26,898.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-11381-90
203
7-9105-52
S-N-1080
2-2690
12875-52
243
10700

The information contained herein is correct as at 30 Mar 2022

OK