**Note: This document has not been finalised.**


# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com


To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 12 May 2022

## Preliminary Advice

| | | | |
|---|---|---|---|
| Insured Vehicle No | : GBE8673E | | |
| TP Vehicle No | : SJK6661B | Accident Date | : 16/03/2022 |
| Make | : BMW 116D | Assignment Date | : 29/03/2022 |
| Date of Inspection | : 30/03/2022 | Est. Duration of Repair | : 4 |
| Inspection At | : TEAMWORK GARAGE PTE LTD (HQ)<br>53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK<br>SINGAPORE 408934 | | |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

| | | |
|---|---|---|
| Repairer's Estimate (Gross) | :S$ | 16,333.15 |
| Revised Amount | :S$ | 5,056.20 |
| Check Items (Estimated) | :S$ | 0.00 |
| Total | :S$ | 5,056.20 |
| | | |
| Lump Sum Repair | :S$ | |

**Total Loss Consideration**

| | |
|---|---|
| New for Old Value | :S$ |
| Pre-Accident Value | :S$ |
| COE / PARF Rebate | :S$ |

| | |
|---|---|
| Salvage Value | :S$ |
| Margin for Repair | :S$ |

**Remarks**

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.