

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Not Withheld
61 Lys & 9700h

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

FAX: 64153727

Recovery After Pain
12 days

Estimate No: ES2290312/AMK

Date: 30 Mar 2022

Policy No: 5119306969-01

Veh Reg No: **SMV5378H**

Make/Model: MAZDA 3 5DOOR HB 1.5

Chassis No: JM6BN24A8H0119617

Engine No: P520401750

Reg. Date: 23/02/2017

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
1 FRONT BUMPER	866.80	1 PC	866.80	✓
2 FRONT BUMPER REINFORCEMENT	693.80	1 PC	693.80	✗
3 FRONT BUMPER SPONGE GARNISH	106.30	1 PC	106.30	✓
4 FRONT BUMPER RIVET PIN	9.80	6 PC	58.80	✓
5 FRONT BUMPER CLIP	5.80	6 PC	34.80	✓
6 FRONT BUMPER NUMBER PLATE GARNISH	95.00	1 PC	95.00	✓
7 FRONT BUMPER INNER BRACKET	37.50	2 PC	75.00	✓
8 FRONT GRILLE HOUSING	158.50	1 PC	158.50	✓
9 FRONT GRILLE MOULDING	385.00	1 SET	385.00	✓
10 FRONT GRILLE LOGO	75.10	1 PC	75.10	✓
11 FRONT GRILLE CHROME	182.50	2 PC	365.00	✓
12 FRONT GRILLE CLIP	5.80	6 PC	34.80	✓
13 FRONT GRILLE TOP GARNISH	313.00	1 PC	313.00	✓
14 FRONT GRILLE TOP GARNISH CLIPS	5.80	6 PC	34.80	✓
15 REAR BUMPER	940.50	1 PC	940.50	✓
16 REAR BUMPER REINFORCEMENT	504.20	1 PC	504.20	✓
17 REAR BUMPER RH SIDE RETAINER	50.85	1 PC	50.85	✓
18 REAR BUMPER RH REFLECTOR	42.50	1 PC	42.50	✓
19 REAR BUMPER RH TOW HOOK COVER	32.50	1 PC	32.50	✓
20 REAR BUMPER RH PDC SENSOR	176.20	2 PC DAM	352.40	✓
21 REAR BUMPER PDC SENSOR WIRE HARNESS	165.80	1 SET	165.80	✓
22 REAR BUMPER CLIP	5.80	6 PC	34.80	✓
23 REAR BUMPER RH INNER SHIELD	86.50	1 PC	86.50	✓
24 REAR TAILGATE	1,508.30	1 PC	1,508.30	✓
25 TAILGATE INNER RUBBER	125.50	1 PC	125.50	✓
26 TAILGATE LOGO	82.50	1 PC	82.50	✓
27 TAILGATE EMBLEM 'MAZDA 3'	58.80	1 PC	58.80	✓
28 TAILGATE EMBLEM 'SKYACTIV'	68.20	1 PC	68.20	✓
29 TAILGATE RH REFLECTOR	421.50	1 PC	421.50	✓
30 TAILGATE OUTER GARNISH	515.20	1 PC	515.20	✓
31 TAILGATE WINDSCREEN GLASS MOULDING	58.50	1 PC	58.50	✓
32 RH TAILLAMP	925.10	1 PC	925.10	✓
33 REAR RH FENDER	1,174.20	1 PC	1,174.20	✓
34 REAR RH FENDER AIR GRILLE	58.50	1 PC	58.50	✓
35 REAR RH FENDER INNER TRIM	315.20	1 PC	315.20	✓
36 REAR SPARE TYRE PANEL RH SIDE SPONGE	105.20	1 PC	105.20	✓
37 REAR END PANEL	505.10	1 PC	505.10	✓
38 REAR END PANEL INNER TOP GARNISH	85.20	1 PC	85.20	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG/AMK
 Claim Type: Third Party
 Accident Date: 26/03/2022
 TP Veh Reg No: SNA4883X

Estimate No: ES2290312/AMK
 Date: 30 Mar 2022
 Policy No: 5119306969-01
 Veh Reg No: SMV5378H
 Make/Model: MAZDA 3 5DOOR HB 1.5
 Chassis No: JM6BN24A8H0119617
 Engine No: P520401750
 Reg. Date: 23/02/2017

Estimate Repair Cost to Vehicle No :SMV5378H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			11,513.75	
		Less 20%	2,302.75	9,211.00
Special Net				
39 FRONT NUMBER PLATE	25.00	1 PC	25.00	✓
40 REAR END PANEL SEALANT	40.00	1 PC	40.00	305.00
41 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
			105.00	105.00
Labour				
42 TOWING FROM TRAFFIC POLICE COMPOUND TO CHENG HOE (KING DOLLY)	100.00	1 LA	100.00	2 ✓
43 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,HEADLAMP & REALIGN BONNET THE SAME	400.00	1 LA	400.00	250.00
44 PUTTY & RESPRAY FRT BUMPER & ATTACHMENTS & ALL AFFECTED AREAS	400.00	1 LA	400.00	320.00
45 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
46 REMOVE & REFIX REAR BUMPER & ATTACHMENTS,PARKING SENSORS,TAILGATE & ATTACHMENTS,TAILLAMPS;TO CUT,WELD & RENEW REAR RH FENDER,REAR END PANEL;KNOCKING & REPAIR REAR SPARE TYRE PANEL,REAR RH WHEEL HOUSING,RH CHASSIS FRAME & REALIGN REAR RH DOOR THE SAME	1,600.00	1 LA	1,600.00	1300.00
47 PUTTY & RESPRAY REAR BUMPER,REINFORCEMENT,PARKING SENSORS,TAILGATE,OUTER GARNISH,REAR END PANEL,REAR SPARE TYRE PANEL,REAR RH FENDER & WHEEL HOUSING,REAR RH CHASSIS FRAME & ALL AFFECTED AREAS	1,400.00	1 LA	1,400.00	1000.00
48 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
49 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	50.00	1 PC	50.00	✓
50 REMOVE & REFIX REAR SEAT,CARPET TO FACILITATE REPAIR	120.00	1 LA	120.00	✓
51 RUSTPROOFING	120.00	1 LA	120.00	90.00
			4,560.00	4,560.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 26/03/2022

TP Veh Reg No: SNA4883X

Estimate No: ES2290312/AMK

Date: 30 Mar 2022

Policy No: 5119306969-01

Veh Reg No: SMV5378H

Make/Model: MAZDA 3 5DOOR HB 1.5

Chassis No: JM6BN24A8H0119617

Engine No: P520401750

Reg. Date: 23/02/2017

Estimate Repair Cost to Vehicle No :SMV5378H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 13,876.00
			Add GST @ 7%	971.32
			Total Amount Payable	<u>S\$ 14,847.32</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn LA

AUTHORISED SIGNATURE