WEARNES

SERVICE ESTIMATE

88159 - C00001 SL: SERVICE SALES - PC

Mdm S Selvam Priyanga
Jurong West St 61
#04-145
Singapore
Singapore 640624

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 31/03/2022
WIP No. . : 19239
Veh.In/Out:
*Tel.No. . : Mobile: 94266175
Reg.No. . : SMQ5953Z
Reg.date .: 11/01/2017
Mileage ..: 0
Chassis No: SAJAB4AN9HCP03110

Closed by .... : Juan Paulo Bongon Ba
Svc Consultant :
Remarks ..... : Mdm Selvam Priyanga

Op.No	Description	Mech Qty	Price	Disc%	Pkg Amount	G
802	TO REPLACE BOOTLID, REAR BUMPE REINFORCEMENT, EMBLEM, BOOTLID LAMP LH, TAIL LAMP LH, ETC	0	3000.00	0	~~3,000.00~~ 2600	S
800	TO SPRAY BOOTLID, REAR BUMPER, ETC	0	2500.00	0	~~2,500.00~~ 2000	S
802	TO REMOVE & TRANSFER BOOTLID INTERIOR COMPONENTS	0	500.00	0	~~500.00~~	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0	~~621.00~~	S
802	TO REPLACE EXHAUST PIPE, ETC Xnn	0	1500.00	0	1,500.00	S
	TRUNK LIP XE 4/ Xnn	1.0 EA	1696.80	1527.12	1,696.80	S
	SEAL-TRUNK LID Xnn	1.0 EA	250.80		250.80	S
	BOOTH LATCH XE XF Xnn	1.0 EA	322.90		322.90	S
	TRUNK LIP BEZEL XE X? Xnn	1.0 EA	25.20		25.20	S
	ACTUATOR X nn	1.0 EA	173.40		173.40	S
	COVER X nn	1.0 EA	18.90		18.90	S

WEARNES

SERVICE ESTIMATE

88159 - C00001 SL: SERVICE SALES - PC

Mdm S Selvam Priyanga
Jurong West St 61
#04-145
Singapore
Singapore 640624

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 31/03/2022
WIP No. . : 19239
Veh.In/Out:
*Tel.No. . : Mobile: 94266175
Reg.No. . : SMQ5953Z
Reg.date .: 11/01/2017
Mileage ..: 0
Chassis No: SAJAB4AN9HCP03110

Closed by .... : Juan Paulo Bongon Ba
Svc Consultant :
Remarks ..... : Mdm Selvam Priyanga

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	BADGE REAR "XE"		1.0 EA	125.00	10.50		125.00	S
	BADGE		1.0 EA	228.90	20.01		228.90	S
	BADGE		1.0 EA	120.30	10.27		120.30	S
	FOG LAMP REAR LH XE		1.0 EA	398.30			398.30	S
	LAMP-TAIL LH		1.0 EA	553.90			553.90	S
	COVER-BUMPER REAR		1.0 EA	1225.00	1102.50		1,225.00	S
	PANEL-VALANCE REAR		1.0 EA	563.60	507.24		563.60	S
	TOW COVER REAR XE		1.0 EA	34.40			34.40	S
	CAP-END RH		1.0 EA	22.20			22.20	S
	CAP-END LH		1.0 EA	22.20			22.20	S
	BUMPER NUT XF		15.0 EA	5.30	71.55		79.50	S
	MOUNTING BRACKET CEN		1.0 EA	158.50			158.50	S
	MOUNTING-BRACKET LH		1.0 EA	132.90			132.90	S
	BUMPER BEAM REAR XE		1.0 EA	696.50			696.50	S
	ANTENNA		1.0 EA	42.80			42.80	S
	PARKING AID SENSOR R	1pc	6.0 EA	271.30	244.17		1,627.80	S
	PIPE & SILENCER		1.0 EA	1742.30			1,742.30	S

WEARNES

SERVICE ESTIMATE

88159 - C00001 SL: SERVICE SALES - PC
Mdm S Selvam Priyanga
Jurong West St 61
#04-145
Singapore
Singapore 640624

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 3
Inv.date. : 31/03/2022
WIP No. . : 19239
Veh.In/Out:
*Tel.No. . : Mobile: 94266175
Reg.No. . : SMQ5953Z
Reg.date .: 11/01/2017
Mileage ..: 0
Chassis No: SAJAB4AN9HCP03110

Closed by .... : Juan Paulo Bongon Ba
Svc Consultant :
Remarks ..... : Mdm Selvam Priyanga

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	CLAMP		1.0 EA	92.20			92.20	S
	HEATSHIELD LH		1.0 EA	60.20			60.20	S
	HEATSHIELD LH		1.0 EA	248.10			248.10	S
	UNDERTRAY LH		1.0 EA	442.80			442.80	S
	UNDERTRAY RH		1.0 EA	443.00			443.00	S

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
4 days
01/04/22 @ 1040
Resp before paint

Labour Total	8,121.00
Parts Total	11,548.40
Package Total	0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Gross Total.	19,669.40
Net.....	19,669.40
GST @ 7.0%	1,376.86
Total.....	21,046.25
Paid.....	0.00
Please Pay..	21,046.25