

Not Authorized  
11 Sep \$11,600/h

AAD2204-

# Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9443E

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 APR 2022

SHD9443E

JTDKB3FU903080508

200303878K

TOYOTA

PRIUS

14/04/2022

SLC9265K/CHINA

24/05/2019

|   | PART                                           |
|---|------------------------------------------------|
| 1 | COVER, REAR BUMPER                             |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER            |
| 1 | COVER, REAR BUMPER, LOWER                      |
| 1 | GUARD, REAR BUMPER, CENTER                     |
| 1 | RETAINER, REAR BUMPER SIDE, LH                 |
| 1 | RETAINER, REAR BUMPER SIDE, RH                 |
| 1 | FILLER, REAR BUMPER EXTENSION, RH              |
| 1 | FILLER, REAR BUMPER EXTENSION, LH              |
| 1 | PANEL SUB-ASSY, BACK DOOR                      |
| 1 | GARNISH SUB-ASSY, BACK DOOR, OUTSIDE           |
| 1 | BOARD ASSY, BACK DOOR TRIM                     |
| 1 | WEATHERSTRIP, BACK DOOR                        |
| 1 | BOARD, BACK DOOR TRIM                          |
| 1 | LENS & BODY, REAR COMBINATION LAMP, RH (UPPER) |
| 1 | LENS AND BODY, REAR LAMP, RH (LOWER)           |
| 1 | LENS & BODY, REAR COMBINATION LAMP, LH (UPPER) |
| 1 | LENS AND BODY, REAR LAMP, LH (LOWER)           |
| 1 | BOX, DECK FLOOR, RH                            |
| 1 | BOX, DECK FLOOR, LH                            |
| 1 | BOARD, REAR FLOOR, NO.1                        |
| 1 | BOX, DECK FLOOR, REAR                          |
| 1 | PANEL ASSY, DECK TRIM SIDE, LH                 |
| 1 | COVER, FLOOR UNDER, NO.1 LH                    |
| 1 | COVER, FLOOR UNDER, NO.2 RH                    |
| 1 | COVER, REAR FLOOR CTR                          |
| 1 | COVER, DECK TRIM, REAR                         |
| 1 | PAN, REAR FLOOR                                |

|    | LIST         |
|----|--------------|
| \$ | R 442.60 ✓   |
| \$ | R 332.70 ✓   |
| \$ | 15.40 ✓      |
| \$ | R 576.30 ✓   |
| \$ | 116.50 ✓     |
| \$ | 117.70 ✓     |
| \$ | 123.70 ✓     |
| \$ | 123.70 X     |
| \$ | R 1,147.80 ✓ |
| \$ | 925.60 ✓     |
| \$ | 259.20 X     |
| \$ | 372.30 X     |
| \$ | 225.20 X     |
| \$ | 451.80 X     |
| \$ | 502.00 X     |
| \$ | 443.30 X     |
| \$ | 502.00 X     |
| \$ | 313.60 X     |
| \$ | 313.00 X     |
| \$ | 519.00 X     |
| \$ | 105.80 X     |
| \$ | 355.90 X     |
| \$ | 175.10 X     |
| \$ | 241.90 X     |
| \$ | 229.90 ✓     |
| \$ | 126.70 X     |
| \$ | R 583.40 X   |



**Trans-cab Auto Services Pte Ltd****AAD2204-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9443E**

|   |                                              |    |     |          |   |
|---|----------------------------------------------|----|-----|----------|---|
| 1 | PANEL SUB-ASSY, BODY LOWER BACK              | \$ | Bz  | 650.30   | ✓ |
| 1 | LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH | \$ | R   | 467.00   | X |
| 1 | SWITCH ASSY, BACK DOOR OPENER                | \$ | Sm  | 179.10   | X |
| 1 | SEAL, REAR BUMPER SIDE, LH                   | \$ | Sm  | 88.50    | X |
| 1 | STAY ASSY, BACK DOOR, LH                     | \$ | Sm  | 242.50   | X |
| 1 | STAY ASSY, BACK DOOR, RH                     | \$ | Sm  | 242.50   | X |
| 1 | HINGE ASSY, BACK DOOR, LH                    | \$ | R   | 61.00    | X |
| 1 | HINGE ASSY, BACK DOOR, RH                    | \$ | R   | 61.00    | X |
| 1 | REAR TAILGATE TOYOTA LOGO                    | \$ | Mc  | 47.90    | ✓ |
| 1 | REAR TAILGATE WORDING 'PRIUS'                | \$ | Mc  | 54.60    | ✓ |
| 1 | REAR TAILGATE WORDING 'HYBRID'               | \$ | Mc  | 54.60    | ✓ |
| 1 | COVER, FRONT BUMPER                          | \$ | Bz  | 516.00   | ✓ |
| 1 | BRACKET, FRONT BUMPER EXTENSION MOUNTING     | \$ | R   | 103.40   | X |
| 1 | REINFORCEMENT SUB-ASSY, FRONT BUMPER         | \$ | Bz  | 716.60   | ✓ |
| 1 | REINFORCEMENT, FRONT BUMPER, NO.2            | \$ | R   | 246.10   | X |
| 1 | ABSORBER, FRONT BUMPER, LOWER                | \$ | CM  | 132.70   | ✓ |
| 1 | ABSORBER, FRONT BUMPER ENERGY                | \$ | Sm  | 79.60    | X |
| 1 | SUPPORT, FRONT BUMPER SIDE, RH               | \$ | Div | 80.10    | ✓ |
| 1 | SUPPORT, FRONT BUMPER SIDE, LH               | \$ | Sm  | 82.30    | X |
| 1 | EXTENSION, FRONT BUMPER, RH                  | \$ | Sm  | 120.10   | X |
| 1 | EXTENSION, FRONT BUMPER, LH                  | \$ | Sm  | 120.10   | X |
| 1 | COVER, FRONT BUMPER HOLE, RH                 | \$ | De  | 29.30    | ✓ |
| 1 | COVER, FRONT BUMPER HOLE, LH                 | \$ | De  | 29.30    | ✓ |
| 1 | UNIT ASSY, HEADLAMP, LH                      | \$ | Sm  | 2,637.60 | X |
| 1 | UNIT ASSY, HEADLAMP, RH                      | \$ | CM  | 2,637.60 | ✓ |
| 1 | GRILLE SUB-ASSY, RADIATOR                    | \$ | CM  | 346.00   | ✓ |
| 1 | GRILLE, RADIATOR, LOWER NO.1                 | \$ | Sm  | 170.10   | X |
| 1 | EMBLEM ASSY, RADIATOR GRILLE                 | \$ | Mc  | 90.80    | ✓ |
| 1 | FENDER SUB-ASSY, FRONT RH                    | \$ | Bu  | 977.80   | ✓ |
| 1 | LINER, FRONT FENDER, RH                      | \$ | Sm  | 206.70   | X |
| 1 | EMBLEM, SIDE PANEL                           | \$ | Mc  | 54.60    | ✓ |
| 1 | FENDER SUB-ASSY, FRONT LH                    | \$ | R   | 977.80   | X |
| 1 | LINER, FRONT FENDER, LH                      | \$ | Sm  | 202.50   | X |
| 1 | EMBLEM, SIDE PANEL                           | \$ | Mc  | 54.60    | X |
| 1 | SUPPORT, RADIATOR, UPPER RH                  | \$ | Bu  | 78.90    | ✓ |
| 1 | SUPPORT, RADIATOR, UPPER LH                  | \$ | R   | 78.90    | X |
| 1 | SUPPORT SUB-ASSY, RADIATOR, UPPER            | \$ | Bz  | 377.10   | ✓ |



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**AAD2204-****SHD9443E**

|              |                                   |    |     |                  |   |
|--------------|-----------------------------------|----|-----|------------------|---|
| 1            | SUPPORT SUB-ASSY, RADIATOR, LOWER | \$ | R   | 409.90           | X |
| 1            | SUPPORT SUB-ASSY, RADIATOR, LH    | \$ | R   | 245.10           | X |
| 1            | SUPPORT SUB-ASSY, RADIATOR, RH    | \$ | Bu  | 245.10           | X |
| 1            | HOOD SUB-ASSY                     | \$ | Bu  | 983.10           | ✓ |
| 1            | HINGE ASSY, HOOD, LH              | \$ | Dir | 58.90            | ✓ |
| 1            | HINGE ASSY, HOOD, RH              | \$ | Dir | 58.90            | ✓ |
| 1            | BRACE, HOOD LOCK SUPPORT          | \$ | R   | 78.30            | X |
| 1            | INSULATOR, HOOD                   | \$ | CM  | 410.90           | ✓ |
| 1            | LOCK ASSY, HOOD                   | \$ | Dir | 135.00           | ✓ |
| 1            | SEAL, HOOD TO FRONT END PANEL     | \$ | Ru  | 51.60            | ✓ |
| 1            | JAR ASSY, WINDSHIELD WASHER       | \$ | Sn  | 219.10           | X |
| 1            | CONDENSER ASSY, COOLER            | \$ | Sn  | 1,783.20         | X |
| 1            | CLEANER ASSY, AIR                 | \$ | Sn  | 1,147.00         | X |
| 1            | BRACKET, HEADLAMP, LH             | \$ | Sn  | 34.80            | X |
| 1            | BRACKET, HEADLAMP, RH             | \$ | Sn  | 34.80            | X |
| 1            | BRACKET, FRONT BUMPER SIDE, LH    | \$ | Sn  | 59.30            | X |
| 1            | BRACKET, FRONT BUMPER SIDE, RH    | \$ | Sn  | 59.30            | X |
| 1            | COVER, RADIATOR SUPPORT OPENING   | \$ | Dir | 235.30           | ✓ |
| <b>TOTAL</b> |                                   | \$ |     | <b>29,187.30</b> |   |
| <b>25%</b>   |                                   | \$ |     | <b>7,296.83</b>  |   |
|              |                                   | \$ |     | <b>21,890.48</b> |   |

**Special Nett**

|                                     |    |     |        |        |
|-------------------------------------|----|-----|--------|--------|
| 1SET PARKING AID                    | \$ | CM  | 700.00 | 220sn  |
| 1SET REAR BUMPER CLIP               | \$ | Ru  | 95.00  | 60sn   |
| 2 WINDSCREEN SEALANT                | \$ | Ru  | 150.00 | 80sn   |
| 1 WINDSCREEN MOULDING               | \$ | Ru  | 200.00 | ✓      |
| 1 WINDSCREEN INNER SPONGE SEAL      | \$ | Ru  | 130.00 | 30sn   |
| 1 REAR TAILGATE STICKER "Trans-Cab" | \$ | Ru  | 80.00  | 30sn   |
| 1 REAR TAILGATE STICKER "6555-3333" | \$ | Ru  | 80.00  | 30sn   |
| 1 REAR BUMPER PROTECTOR             | \$ | RSP | 180.00 | X      |
| 2 SEAM SEALANT                      | \$ | Ru  | 250.00 | X      |
| 1SET REAR BUMPER RETAINER CLIP      | \$ | Ru  | 85.00  | 60sn X |
| 1 REAR NUMBER PLATE WITH HOLDER     | \$ | Ru  | 140.00 | 45sn   |
| 1SET TAILLAMP LOWER CLIP            | \$ | Ru  | 55.00  | X      |
| 1SET TAILLAMP UPPER CLIP            | \$ | Ru  | 55.00  | X      |
| 1 END PANEL TRIM CLIP               | \$ | Ru  | 65.00  | X      |



**Trans-cab Auto Services Pte Ltd**

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9443E**

|                                    |           |                 |      |
|------------------------------------|-----------|-----------------|------|
| 1 REAR SPOILER CLIP                | \$        | nn 70.00        | 60X  |
| 1SET BUMPER CLIP FRT               | \$        | nn 95.00        | 60sn |
| 1 FRONT NUMBER PLATE WITH MOULDING | \$        | Ry 200.00       | 45sn |
| 1SET CLIP, FRONT FENDER LINER      | \$        | nn 85.00        | X    |
| 1SET FRNT BUMPER RETAINER CLIP     | \$        | nn 85.00        | X    |
| 1 HOOD INSULATOR CLIP              | \$        | nn 55.00        | ✓    |
| <b>TOTAL</b>                       | <b>\$</b> | <b>2,855.00</b> |      |

**TOTAL PARTS \$ 24,745.48****LABOUR**

|                                                                                                                           |    |           |       |
|---------------------------------------------------------------------------------------------------------------------------|----|-----------|-------|
| To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.                                      | \$ | 300.00    | 180l  |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | 380.00    | 80l   |
| To transfer of luggage floor panel fittings, attachment and perform water seepage test.                                   | \$ | 380.00    | X     |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 2,200.00  | 1400l |
| To transfer of rear end panel fittings, attachment and perform water seepage test.                                        | \$ | 380.00    | X     |
| To transfer of Tailgate fittings, attachments and perform water seepage test.                                             | \$ | 180.00    | 60l   |
| To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.                   | \$ | nn 480.00 | X     |
| To transfer of Fender fittings, attachments and perform water seepage test.                                               | \$ | nn 480.00 | X     |
| To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.                                              | \$ | 380.00    | 100l  |

LKK Auto Care, Singapore

(PART-BY-PART) Repair Days

25 DAY

100 days

Acknowledged by Repairer

Signature:

Date:



**Trans-cab Auto Services Pte Ltd**

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9443E**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ ~ 380.00 X

To check steering geometry and computer wheel alignment

\$ ~ 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 Pol

Towing Fees

\$ 150.00 Sol

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 176ol

To reinstall rear bumper parking sensor.

\$ 170.00 Sol

To Check Electrical Lighting Concerned.

\$ 170.00 4ol

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ ~ 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ ~ 220.00 X

To replace, refix and top up coolant for radiator

\$ ~ 170.00 X

To lift-up / out engine with gear box and refit.

\$ ~ 440.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ ~ 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ ~ 380.00 X

**TOTAL \$ 10,290.00****Over All Total \$ 35,035.48****(PART-BY-PART) Repair Days****25 DAYS****10 days**

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: