Ass. Rec. By: REF: CS/FCI22003581/Any3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: XE4533S Yr Regn: 2018, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Man TGS32 c.c 10518

Colour white A/C: Insured / Std / NI / NA

Sp.Reading 156242 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WMA49SZ23KM802562

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: 295/80R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	21/04/22

Survey held at Joo Koon Circle.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.
	preli report
	submit final fig: $ 24,581.25 and 14 days
	MV : (red, $1068.75, 4%)
	PV :
	Nett :
	11SD.

Date/Time, File Pass to? ☐ : Preli. Report

1) 27/01/23 ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

☐ : Weekend ($

Survey Fee:

Transportation: $ + RS $

Photos

Other:

Report Format : tp

Lump Sum / LP Fee : 24581.25