Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

TOYOTA

TP/DS

18 Days.
limit repair
After repair photos
Eng Qiang. 8288 0282
19/4/22

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept Liability Check Vehicle "Grounded"	S1000005 / ICFIC1 Document No. 0 Document Date 19/04/2022	Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433	1NZY079462	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-MS SUNDRIES TP VEH:SHD6130C ACC DATE:14/04/2022 TP INS:1ST CAPITAL NO OF REPAIR DAYS: TOW-IN:14/04/2022 DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				30.00
2	S	BP-SUBLET TO SUPPLY FRONT NUMBER PLATE WITH CASING.				68.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-MECH2 R/I AIRCON CONDENSER/RADIATOR TO FACILIATE REAPIRS.				? 360.00
5	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.				122.40
6	B	BP-LAB2 TO REPLACE FRONT ACCIDENT DAMAGE PARTS. 720x3=2160 STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS. 590x3			2160	4320.00
7	B	BP-RES2 TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS.			1770	3540.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR BOOTLID,REAR END PANEL AND SPARE TYRE PANEL.				180.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Raymond - 9776 2689

Customer Copy

Borneo Motors

Inchcape

TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1 Document No. 0 Document Date 19/04/2022	Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433	1NZY079462	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-MECH2 R/I REAR EXHAUST PIPE TO FACILIATE REPAIRS.				720.00
10	B	BP-MECH2 R/I FUEL TANK AND ATTACHMENT TO FACILIATE REPAITS.			462	720.00 436.00
11	B	BP-WS R/I REAR WINDSCREEN TO FACILIATE REPAIRS.				122.40
12	B	BP-LAB2 TO CONDUCT WATER LEAK TEST.				180.00
13	B	BP-LAB2 R/I REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.				360.00
14	B	BP-LAB2 TO TRANSFER REAR BOOTLID MECHANISM TRIMMING AND OTHER ATTACHMENT				720.00
15	B	BP-LAB2 R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS. 720 x 8			5760	7200.00
16	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS. 850 X 7			4130	5900.00
17	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.				68.00
18	S	BP-SUBLET TO SUPPLY REAR NUMBER PLATE WITH CASING.				730.50
19	1	S81110-0D310 HEADLAMP ASSY, RH ~~X~~ NN	1.00	730.50		

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

Borneo Motors

Inchcape

TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611. Tel no. 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1 Document No. 0 Document Date 19/04/2022	Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433	1NZY079462	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd		Job/Parts Description	Qty	Unit Price	Disc %	Amount
20	2	S81150-0D310	HEADLAMP ASSY, LH ~~2~~ NN	1.00	730.50		730.50
21	3	S85315-0D101	JAR, WASHER, A ~~2~~ NN	1.00	154.60		154.60
22	4	S88460-0D390	CONDENSER ASSY ~~2~~ NN	1.00	1678.00		1678.00
23	5	S16400-0M070	RADIATOR ASSY ~~2~~ NN	1.00	2343.30		2343.30
24	6	S16361-0M050	FAN ~~2~~ NN ~~2~~ NN	1.00	257.70		257.70
25	7	S16711-0M030	SHROUD, FAN / RE	1.00	314.90		314.90
26	8	S52119-0D996	COVER, FR BUMPER, L ~~2~~ MIS	1.00	525.80		✓ 525.80
27	9	S52721-0D902	MOULDING, FR BUMPER ~~2~~ NN	1.00	16.30		✓ 16.30
28	0	S53112-0D120	GRILLE, RADIATOR, LW ~~2~~ NN	1.00	97.20		97.20
29	1	S52021-0D090	REINFORCEMENT SUB-AS ~~2~~ NN	1.00	423.90		423.90
30	2	T52011-52021	ARM SUB-ASSY, FR ~~2~~ NN	1.00	276.60		276.60
31	3	T52012-52020	ARM SUB-ASSY, FR ~~2~~ NN ~~2~~ NN	1.00	224.50		224.50
32	4	S53164-0D031	BRACKET, RADIATOR SU ~~2~~ NN	1.00	62.30		62.30
33	5	S53165-0D031	BRACKET, FR BUMPER S ~~2~~ NN	1.00	62.30		62.30
34	6	S52617-0D050	ABSORBER, RADIATOR S ~~2~~ NN	1.00	116.60		116.60
35	7	S52535-0D061	RETAINER,FR BUMPER S ~~2~~ NN	1.00	68.40		68.40
36	8	S52536-0D061	RETAINER FR BUMPER S ~~2~~ NN	1.00	68.40		68.40
37	9	T90159-50353	SCREW, W/WASHER ~~2~~ NN	2.00	2.20		4.40
38	0	S53111-0D300	GRILLE,RADIATOR / CUT	1.00	490.50		✓ 490.50
39	1	S75301-0D010	EMBLEM SUB-ASSY, FR / RE	1.00	71.60		✓ 71.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	
		Labour	Less
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Customer Copy

Borneo Motors
Inchcape

TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1 Document No. 0 Document Date 19/04/2022	Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433	1NZY079462	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
40	2	S53201-0D130	SUPPORT SUB-ASSY, RA ~~R~~ NN	1.00	1138.00		1138.00
41	3	S53221-0D010	BRACE, RADIATOR SUPP ~~R~~ NN	1.00	101.60		101.60
42	4	S53222-0D010	BRACE, RADIATOR SUPP ~~R~~ NN	1.00	101.60		101.60
43	5	S53285-0D061	SEAL RADIATOR SIDE A ~~R~~ NN	1.00	28.20		28.20
44	6	S53286-0D061	SEAL,RADIATOR SIDE A ~~R~~ NN	1.00	28.20		28.20
45	7	S53287-0D031	EXTENSION,RADIATOR S ~~R~~ NN	1.00	47.80		47.80
46	8	S53288-0D031	EXTENSION RADIATOR ~~R~~ NN	1.00	48.70		48.70
47	9	S53301-0D100	HOOD SUB-ASSY X Repair	1.00	664.00		664.00
48	0	S53510-0D181	LOCK ASSY, HOOD X	1.00	111.00		111.00
49	1	S53410-0D170	HINGE ASSY, HOOD, RH X } Repair	1.00	57.80		57.80
50	2	S53420-0D170	HINGE ASSY, HOOD, LH X	1.00	57.80		57.80
51	3	SPZ061-0D014 00	PRIMER SENSOR / Ent	1.00	162.66		✓162.66
52	4	S17430-0M061	PIPE ASSY, EXHUAST T ~~R~~ NN	1.00	879.20		879.20
53	5	S17565-0M020	SUPPORT, EXHAUST PIP ~~R~~ NN	3.00	24.70		74.10
54	6	S81550-0D330	LAMPASSY,RRCOMBINATI / } ORA	1.00	291.40		✓291.40
55	7	S81560-0D330	LAMPASSY,RRCOMBINATI	1.00	291.40		✓291.40
56	8	T81497-52030	COVER, RR ~~R~~ NN	1.00	3.50		3.50
57	9	T81498-52030	COVER, RR ~~R~~ NN	1.00	3.50		3.50
58	0	T81496-52020	GUIDE, RR ~~R~~ NN	4.00	2.70		10.80
59	1	S81910-0D010	REFLECTOR ASSY, REFL / ORA	1.00	97.90		✓97.90

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

Borneo Motors

inchcape

TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1 Document No. 0 Document Date 19/04/2022	Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433	1NZY079462	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
60	2	S81920-0D010	REFLECTOR ASSY, REFL	1.00	97.90		97.90
61	3	S52159-0D983	COVER, RR BUMPER L/C	1.00	525.80		525.80
62	4	S52161-0K040	PIECE, RR BUMPER	4.00	4.30		17.20
63	5	S52575-0D070	RETAINER, RR BUMPER	1.00	109.20		109.20
64	6	S52576-0D070	RETAINER, RR BUMPER	1.00	109.20		109.20
65	7	S52155-0D030	SUPPORT, RR BUMPER S	1.00	36.90		36.90
66	8	S52156-0D030	SUPPORT, RR BUMPER S	1.00	36.90		36.90
67	9	S52591-0D080	SEAL, RR BUMPER SIDE	1.00	53.60		53.60
68	0	S52592-0D080	SEAL, RR BUMPER SIDE	1.00	53.60		53.60
69	1	S58307-0D101	PANEL SUB-ASSY, BODY	1.00	738.00		738.00
70	2	S58311-52210	PAN RR FLOOR	1.00	739.90		739.90
71	3	S58327-0D081	INSULATOR, MAIN MUFF	1.00	45.60		45.60
72	4	S61601-0D160	PANEL SUB-ASSY, QUAR	1.00	1115.30		1115.30
73	5	S61063-0D010	TROUGH SUB-ASSY, LUG	1.00	136.10		136.10
74	6	S61602-0D180	PANEL SUB-ASSY, QUAR	1.00	1115.30		1115.30
75	7	S61064-0D010	TROUGH SUB-ASSY, LUG	1.00	136.10		136.10
76	8	T08826-08115	PANEL BONDING AD	2.00	267.20		534.40
77	9	S62940-06030	DUCT A/S, QTR VENT	1.00	144.90		144.90
78	0	S75573-0D050	MOULDING,BACK W/D,OS	1.00	87.20		87.20
79	1	T64813-52080	DAM, BACK WINDOW	1.00	45.70		45.70

DIS
X NN
DIS

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

Borneo Motors
Inchcape

TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1 Document No. 0 Document Date 19/04/2022	Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433	1NZY079462	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
80	2	T21000-20	SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
81	3	T21000-22	SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
82	4	S64401-0D090	PANEL SUB-ASSY, LUGG	1.00	706.10		706.10
83	5	S64461-0D050	WEATHERSTRIP, LUGGAG	1.00	205.80		205.80
84	6	T64503-12150	ARM SUB-ASSY, LUG X NN	2.00	62.70		125.40
85	7	S64610-0D030	LOCK ASSY, LUGGAGE C	1.00	112.90		112.90
86	8	S64621-06050	STRIKER, LUGGAGE COM	1.00	11.30		11.30
87	9	S58387-0D010	PLATE, RR FLOOR FINI	1.00	236.40		236.40
88	0	T90467-08186 B4	CLIP	2.00	2.90		5.80
89	1	S64995-0D030	BOX, DECK FLOOR, RH	1.00	251.50		251.50
90	2	S64997-0D030	BOX, DECK FLOOR, LH	1.00	201.40		201.40
91	3	S64770-06120	COVER ASY,SPARE WHL	1.00	252.70		134.3 252.70
92	4	S64743-0D010	DOOR, DECK SIDE BOX,	1.00	62.60		62.60
93	5	S64744-0D010	DOOR, DECK SIDE BOX,	1.00	47.80		47.80
94	6	S64727-0D020	PAD, LUGGAGE COMPART	1.00	302.90		302.90
95	7	S64711-0D080 C0	MAT, LUGGAGE COMPART	1.00	425.80		425.80
96	8	S64719-0D030 C0	COVER,LUGGAGECOMPART X NN	1.00	199.50		199.50
97	9	S75442-0D070	PLATE, LUGGAGE COMPT	1.00	52.10		52.10
98	0	S75431-02090	EMBLEM, LUGGAGE COMP	1.00	65.30		65.30
99	1	S75444-0D070	PLATE, LUGGAGE COMPT	1.00	44.00		44.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

Borneo Motors

Inchcape

TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	Account No. S1000005 / ICFIC1 Document No. 0 Document Date 19/04/2022	Mdm Yeo Ling May 10 Limau Terrace Singapore 465808 Mobile: 92340335

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2010	NCP93R	BEPGKT G1	12/11/2010	SJZ3073P	0	21740	69DS/SJZ3073P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053HY9305161433	1NZY079462	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
100	2	S76801-0D906	GARNS/A,LUGCOMPTDOOR	1.00	200.00		200.00
101	3	T58651-22H91	SHEET, RR FLOOR	1.00	219.90		219.90
102	4	T90269-06017	RIVET	2.00	4.00		8.00
103	5	S08889-80102	COOLANT,SLLC&&&	2.00	84.30		168.60

X NN

LKK Auto Consultants hence notify the Repairer of the following:
- To resume ... after spray painting
- ... during resurvey
- ... confirmation
- ... but Prejudice basis
- ...
- ... surveyed and ... Insurance Company

Acknowledged by Repairer
Signature:
Date:

For & on behalf of
Borneo Motors (Singapore) Pte Ltd

Customer's Signature

Please acknowledge receipt of vehicle

Charge Summary	
Parts	23,118.06
Labour	25,090.80
Sublet	136.00
Lubrication/Fluid	0.00
Others	0.00

Total	48,344.86
GST 7.00%	3,384.14
Less	0.00
Amount Due	51,729.00

Customer Copy