REF: NTHC

4/25/22, 10:50 AM

ASSIGNMENT

Yr Regn: 23/4 119

Repairer Estimates

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY		
Policy No:		Ref. No:	
Vehicle Reg. No.:	**SHC3776P**	Date of Loss:	24/04/2022
Party At Fault:	UNKNOWN	Driveable?	YES
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)		
Vehicle Colour:	BLUE	Vehicle Reg. Date:	31/08/2021
Engine No:	G4LEKU422801	Gen Condition:	GOOD
Odometer:	0 KM	Chassis No:	KMHC851CVLU193241
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	**NO**		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	3,709.80
Miscellaneous Items	11.00
Labour	1,770.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S$)	**5,490.80**
+ GST 7.00% (S$)	384.36
Nett Amount (S$)	5,875.16

This claim is handled by: JUMANI BIN MASUDIN

*Generated using **Merimen** e-Claims Internet Estimation & Adjusting System*

REF: N4C

ASSIGNMENT

4/25/2 . 10:50 AM

Est nates on Miscellaneous Items

Repairer Estimates

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
		Sub Total (S$)	**11.00**

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEAT	New	900.00
2	SPRAYPAINT	New	600.00
3	TUFF KOTE	New	50.00
4	CHECK WIRING	New	50.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00
6	REMOVE/REFIX REVERSE SENSOR	New	50.00
		Gross Labour Cost (S$)	**1,770.00**

ComfortDelGro Engineering Pte Ltd/SHC3776P/25/04/2022 10:50. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

F: 5194.28

RD: 3

Thwin
87235764
25/4/22 1630
P/P 3days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BY: Thean | REF: Ntuc

ASSIGNMENT

SJH9444T Yr Regn: 2314 119

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Apr 2022)
Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: **ComfortDelGro Engineering Pte Ltd/SHC3776P/25/04/2022 10:50**
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*BOOTLID COVER	2480.40	20.00	0.00	*2,549.70 FL
2	1		*REAR BUMPER ASSY		20.00	0.00	*459.40 FL
3	10		*REAR BUMPER CLIIPS		20.00	0.00 22	*220.00 FL
4	1		*REAR BUMPER TOW COVER		20.00	0.00	*98.80 FL
5	1		*REAR BUMPER CENTRE GUIDE		0.00	0.00	*451.25 FL
6	1		*REAR BUMPER MAT		0.00	0.00	*50.00 F
7	1		*REVERSE SENSOR		0.00	0.00	*180.00 F
8	1		*REAR NUMBER PLATE		20.00	0.00	*50.00 F
9	1		*FOG LAMP		20.00	0.00	*201.50 FL
10	1		*ANTENNA SMARTKEY		20.00	0.00	*40.50 FL
11	1		*BOOTLID EMBLEM - IONIQ		20.00	0.00	*31.30 FL
12	1		*BOOTLID EMBLEM - HYBRID		20.00	0.00	*24.30 FL
13	1		*BOOTLID EMBLEM - H		0.00	0.00	*28.00 FL
14	1		*BOOTLID COMFORTDELGRO LOGO		0.00	0.00	*30.00 F
15	1		*BOOTLID COMFORT TEL.NOS STICKER		0.00	0.00	*30.00 F
16	1		*BOOTLID APPS LOGO		0.00	0.00	*40.00 F
17	2		*WINDSCREEN GLASS SEALANT		0.00	0.00	*46.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S$)	**4,530.75**
- List Item Discount on L Items (S$)	820.95
Total Parts (S$)	**3,709.80**

ComfortDelGro Engineering Pte Ltd/SHC3776P/25/04/2022 10:50. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Sup: Stay Lfl: crq 138.10

(2) bumber beam: clt 394.80

(3) moulding lower centre: Cut 155