

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1	Tailgate	1,295.60	1,295.60	
2	Tailgate inner trim board	455.20	910.40	
3	Tailgate weatherstrip	381.80	381.80	
4	Tailgate inner lock	412.60	412.60	
2 pcs	Tailgate damper @ SGD 231.00	462.00	924.00	
6	Tailgate windscreen moulding	97.40	584.40	
7	Tailgate logo	98.60	98.60	
8	Tailgate chrome moulding garnish	386.70	386.70	
2 pcs	Tailgate lamp @ SGD 586.70 (LED - White)	1,173.40	1,173.40	
2 pcs	Taillamp assy @ SGD 780.90 (LED - White)	1,561.80	1,561.80	
2 pcs	Taillamp panel @ SGD 297.40	594.80	594.80	
12	Rear bumper	856.40	856.40	
2 pcs	Rear bumper side retainer @ SGD 120.20	240.40	240.40	
2 pcs	Rear bumper bracket @ SGD 68.20	136.40	136.40	
2 pcs	Rear bumper reinforcement bracket SGD 102.60	205.20	205.20	
16	Rear bumper tow cover	48.60	48.60	
2 pcs	Rear bumper reflector @ SGD 145.70	291.40	291.40	
18	Rear spare tyre top board	296.30	296.30	
19	Rear spare tyre bracket	455.70	455.70	
20	Rear spare tyre panel	937.10	937.10	
21	Rear spare tyre foam N/S	298.70	298.70	
22	Rear spare tyre Foam O/S	275.60	275.60	
2 pcs	Rear fender inner trim garnish @ SGD 495.80	991.60	991.60	
2 pcs	Rear fender inner shield @ SGD 175.80	351.60	351.60	
25	Rear end panel inner	651.80	651.80	
26	Rear end panel outer	629.40	629.40	
27	Rear end panel top garnish	298.60	298.60	
28	Rear exhaust pipe	920.40	920.40	
29	Rear exhaust centre pipe	146.80	146.80	
2 pcs	Rear exhaust pipe mounting @ SGD 95.40	190.80	190.80	
31	Rear antenna sensor	113.50	113.50	
		Parts :	\$ 15,142.70	
		Less Parts 25% :	\$ 3,785.67	
		Total Parts :	\$ 11,357.02	

Special Net Items :

1 set	Rear bumper clips	nee	\$	60.00	50
	Rear tailgate inner trimboard clips	nee	\$	50.00	40
	Tailgate windscreen primer & cleaner	nee	\$	100.00	40
	Tailgate windscreen sealant	nee	\$	80.00	40
	Tailgate sealant	nee	\$	80.00	50
	Rear fender inner trim garnish clips	11	\$	80.00	X
	Rear end panel top garnish clips	11	\$	40.00	X
	Rear end panel sealant	nee	\$	80.00	50
	Rear floor panel sealant	11	\$	80.00	X
	Rear floor panel insulation padding	11	\$	150.00	X
	Rear number plate w/garnish	CR	\$	55.00	40
	Reverse sensor w/module	SW	\$	280.00	200
			Total S/N Parts :	\$ 1,135.00	

Labour :

To Repair, Remove & Renew On Affected Rear Accident Areas @ SGD 300.00 per day	\$	1,500.00	850
To Putty, Spray Paint on Affected Rear Accident Areas @ SGD 300.00 per panel (Rear bumper, fenders, tailgate, end panel, floor panel)	\$	1,600.00	1100
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Remove & Transfer Tailgate Components to Facilitate Repairs	\$	120.00	60
To Remove & Install Rear Tailgate Glass to Facilitate Repairs	\$	150.00	120
To Remove & Install Rear Spare Tyre Compartment, Trims, Garnish to Facilitate Repairs	\$	150.00	80
To Remove, Align & Install Rear Exhaust Pipe	\$	150.00	60
To Install, Drill & Re-position Reverse Sensor	\$	150.00	50
To Rust Proof Affected Areas	\$	250.00	60
To Conduct Nano Coating on Affected Areas	\$	500.00	X
Total Labour :		\$	4,620.00

TOTAL PARTS :	\$	11,357.02
TOTAL SPECIAL NET ITEM:	\$	1,135.00
TOTAL LABOUR :	\$	4,620.00
TOTAL REPAIR COST :	\$	17,112.02

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 7160-90
252

P- 5370-67

S.N- 510.00

L- 2400.00

8280.67

292

6624.