

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

Name : Akif Bin Samsodin
(93397475)

Accident Date : 24-Apr-22

Vehicle No : FBQ4514J

Yamaha Aerox

Vehicle Model : GDR155A

CVT ABS

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fork assy <i>SVL</i>	\$ 980.00 X
1	Fork under bracket <i>11</i>	\$ 190.00 X
1	Front sport rim <i>11</i>	\$ 550.00 X
1	Front brake disc <i>11</i>	\$ 180.00 X
1	Front rim shaft <i>11</i>	\$ 52.00 X
1	Front rim bearing <i>11</i>	\$ 48.00 X
1	Headlamp <i>11</i>	\$ 500.00 X
1	Side mirror (1 set) <i>220</i>	\$ 120.00 ✓
1	Handle-bar <i>11</i>	\$ 135.00 ✓
1	Handle-bar balancer (1 set) <i>CU1</i>	\$ 30 80.00 ✓
1	Hand grip (1 set) <i>11</i>	\$ 60.00 X
2	Brake lever <i>M/S CU1 o/s n n</i>	\$ 55 110.00 1 pc
1	Front side inner cover <i>CU1</i>	\$ 195 210.00 ✓
1	Radiator cover <i>o/s 7011</i>	\$ 167.00 ✓
2	Footstep panel <i>CU1/7011</i>	\$ 510.00 ✓
2	Footstep panel lower cover <i>DIS</i>	\$ 340.00 ✓
1	Rear footrest <i>CU1</i>	\$ 60 168.00 ✓
1	Exhaust assy <i>DIS</i>	\$ 680.00 ✓
1	Exhaust protector <i>DIS</i>	\$ 48.00 ✓
1	Rear signals <i>n/s CU1</i>	\$ 90 180.00 ✓
1	Fairing cover (1 set) <i>CU1</i>	\$ 900 1,450.00 ✓
1	Rear rim <i>12</i>	\$ 680.00 X
1	Engine cover <i>CU1</i>	\$ 500 580.00 ✓
1	V belt cover <i>CU1</i>	\$ 285.00 ✓
1	Air filter cover <i>CU1</i>	\$ 125.00 ✓
		\$ 8,428.00
		Less 10%
		\$ 842.80
		\$ 7,585.20

Receptor 20/pun \$ 620 480 ✓

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

Name : **Akif Bin Samsodin**
(93397475)

Accident Date : **24-Apr-22**

Vehicle No : **FBQ4514J**

Yamaha Aerox
Vehicle Model : **GDR155A**
CVT ABS

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	per	\$	38.00	20
2	Fork oils	11	\$	30.00	X
2	Fork oil seals	11	\$	56.00	X
1	Steering cone (1 set)	11	\$	120.00	X
1	"AEROX" embleen	per	\$	60.00	✓
1	Rear box	C 45	\$	3,810.00	300
1	Rear box bracket	Best	\$	180.00	120
1	E.R.P IU	Dame	\$	180.00	165
1	Sticker (1 set)	11	\$	120.00	80
				\$	4,594.00

S/No. Labour

1	To provide towing (LOD) \$50.00	\$	-
2	To provide wiring and reset headlamp focusing	\$	11 80.00 X
3	To re-align body frame	\$	11 450.00 X
4	To provide labour	\$	420.00 } 20
		\$	950.00

Grand Total

\$ 13,129.20

Singapore Dollars: Thirteen Thousand One Hundred Twenty-Nine and Cents: Twenty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: