COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH7883E
Make : HYUNDAI
Model : IONIQ(G3)

Date: 28.04.2022
Insurance: NTUC
MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			$459.40
10	REAR BUMPER CLIPS			$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			$451.25
1	REAR BUMPER REINFORCEMENT			$394.80
1	ANTENNA SMARTKEY			$40.50
1	REAR BUMPER FOG LAMP			$201.50
1	LICENCE LAMP			$85.30
1	REAR BUMPER LOWER CTR MOULDING			$155.00
	SUB TOTAL		473.25	$1,809.75
	LESS 20%		378.60	$361.95
	DISCOUNTED TOTAL			**$1,447.80**
	REAR BUMPER RUBBER MAT			$50.00
	REAR NUMBER PLATE WITH TRIM COVER		-10%	$55.00
	REAR BUMPER REVERSE SENSOR		235 -10%	$180.00
			211.50	**$285.00**
	Labour Charge			
	PANEL BEATING			350 $400.00
	SPRAY PAINTING CHARGE			250 $300.00
	CHECK ALL LIGHTING		630	$60.00
	REMOVE/REFIX REVERSE SENSOR			30 $80.00
	TOTAL LABOUR		1220.10	**$840.00**
	ESTIMATE TOTAL		L/S $1000	**$2,572.80**
			2 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjim 97495749
wp' 28/4/22 @ 4.30pm
L/S Resurvey after repair
2 days
tanjim@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: