LKK Auto Consultants Pte Ltd
Company Registration No. 199607198R
51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 2022 22004687FR

Date: 21st Dec 2022

Our Ref: CS6/AIS22004062/Gny3e2

M/s Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SMN 6024P ACCIDENT ON 28/04/2022

We thank you for your instruction on 29/04/2022.

The following vehicle information was recorded:

Registration Number	: SMN 6024P
Make & Model	: Toyota Prius Plus (Auto)
Chassis Number	: JTDZS3EU10J039060
Year of Registration	: 2019
Engine Capacity	: 1798 cc

1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.

3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.