



NPH AUTO SERVICE

05 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Registration No. QAF 51

cecilia

Ref :
Ref : TP0022/05/22

Page : 1/2
Date : 10/05/2022

THIRD PARTY CLAIM

M/S : YI LENG ELECTRONICS SERVICES
BLK 178 EDGEFIELD PLAINS
#12-230
SINGAPORE 820178

Attn :
Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GBH9764D - TOYOTA PROACE
INSURED : YI LENG ELECTRONICS SERVICES
DATE OF ACCIDENT : 07/05/2022
POLICY NO : DMCVSNW00142022103

ENGINE#
CHASSIS#

Not Authorized
9/5/22
4/5 7000
Tel: 974 1111
6 days

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

Replacement of Parts

		Qty	U/Cost \$	U/Price \$	Total \$
1	rear door RH <i>300gms</i>	1@	1955.80	1955.80	1,955.80
2	rear door hinge bottom <i>300gms</i>	1@	218.50	218.50	218.50
3	rear door hinge top <i>11</i>	1@	218.50	218.50	218.50 X
4	rear door inner wood board <i>11</i>	1@	325.60	325.60	325.60 X
5	rear door inner wood board clips <i>11</i>	9@	5.00	5.00	45.00 X
6	rear boot emblem <i>11</i>	1@	145.80	145.80	145.80
7	rear boot lock lower <i>11</i>	1@	182.90	182.90	182.90 X
8	rear lamp assy RH <i>11</i>	1@	385.50	385.50	385.50
9	rear boot rubber <i>11</i>	1@	295.30	295.30	295.30 X
10	rear bumper <i>11</i>	1@	792.20	792.20	792.20
11	rear bumper side retainer RH <i>11</i>	1@	155.50	155.50	155.50
12	rear bumper reflector lamp RH <i>11</i>	1@	142.30	142.30	142.30
13	rear bumper reinforcement <i>11</i>	1@	688.40	688.40	688.40
14	rear lamp rocker panel outer RH <i>11</i>	1@	385.20	385.20	385.20
15	rear bumper inner end panel <i>11</i>	1@	582.70	582.70	582.70 X
16	rear fender RH <i>11</i>	1@	1958.50	1958.50	1,958.50
17	rear fender air scoop grille <i>11</i>	1@	195.40	195.40	195.40
18	rear fender inner cowling RH <i>11</i>	1@	238.60	238.60	238.60
19	rear fender inner cowlimg clips <i>11</i>	8@	5.00	5.00	40.00
20	rear bumper lower cowling joint RH <i>11</i>	1@	128.80	128.80	128.80
21	rear lamp rocker panel <i>11</i>	1@	488.90	488.90	488.90
					9,569.40
Less 25%					-2,392.35
Total Material					\$7,177.05
Special Nett Items					
22	rear windscreen sealant <i>11</i>	1@	45.00	45.00	45.00



NPH AUTO SERVICE

005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Ref :
Ref : TP0022/05/22

Page : 2/2
Date : 10/05/2022

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
33 rear bumper parking sensor <i>1 set started</i>	10	200.00	200.00	200.00
				245.00

Total S/Nett
Labour & Misc

\$245.00

- 1 Remove & install rear windscreen.
- 2 Remove & install r/lamp, r/door, r/bumper, bumper reinforcement, cut out & renew r/lamp panel, bumper lower rocker panel, r/fender RH, knock r/fender inner panel, floorboard panel and restraighthen body & chassis.
- 3 Car-O-Liner.
- 4 Check wiring system.
- 5 Renew parking sensor.
- 6 Spray painting.
- 7 Remove & install r/finisher and board.
- 8 Towing fee with ramp.

100.00

1400 1,800.00

11 X 350.00

25.00

50 80.00

1000 1,300.00

80 150.00

11 X 120.00

3,925.00

Total Labour

\$3,925.00

Nett Total Before Gst

\$11,347.05

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-7843.60

252

P-5882.7

S.N-240

L-2655

8777.7

202

702