

KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

RAGE

Date :

Total Pages :

TO: Lonpac Insurance Bhd
300, Beach Road, 07
The Concourse, #17-04
Singapore 199555

Our Customer : Empire Cleaning

Vehicle No : **GHB4364H**

Model : Nissan NV350

Manufacture Year : 2020

Date of Accident : 6/5/2022

Total Estimate Repair Days :

Attn : Motor Claim Department

Email : customer_sg@lonpac.com

Re: Repair Estimate For Third Party Claim against : XD3972U

nett item

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front Bumper	1	\$573.90	\$573.90	20/cu7 ✓
2	Front Bumper Clip	6	\$5.00	\$30.00	11X
3	Front bumper side retainer - LH	1	\$165.50	\$165.50	11X
4	LH Front Headlamp	1	\$485.50	\$485.50	CNE ✓
5	LH Corner Panel	1	\$535.60	\$535.60	DD ✓
6	LH Corner Panel Clip	2	\$5.00	\$10.00	11X
7	LH Front Door	1	\$1,073.40	\$1,073.40	D.S ✓
8	LH Front Door Outer Handle	1	\$118.80	\$118.80	CNE ✓
9	LH Front Door Outer Moulding	1	\$157.80	\$157.80	D.S ✓
10	LH Front Door Lock	1	\$172.30	\$172.30	7W1 ✓
11	LH Front Door Lock Cable	1	115.00	115.00	11X
12	LH Front Door Lock Switch	1	\$74.50	\$74.50	11X
13	LH Front Door Hinge	2	\$59.00	\$118.00	BMP ✓
14	LH Front Door Checker	1	\$58.60	\$58.60	7W1 ✓
15	LH Front Door Power Window Regulator	1	\$155.30	\$155.30	11X
16	LH Front Door Glass Channel Weather	1	\$73.80	\$73.80	7W1 ✓
17	LH Front Door Weatherstrip	1	\$158.60	\$158.60	7W1 ✓
18	LH Front Door Inner Trim Board	1	\$504.60	\$504.60	11X
19	LH Front Door Under Rubber Seal	1	\$50.20	\$50.20	11X
20	LH Side Mirror Assy	1	\$553.90	\$553.90	CNE ✓
21	LH Side Mirror Assy Inner Cover	1	\$35.30	\$35.30	11X
22	LH Front Step Panel	1	\$118.30	\$118.30	11X
23	LH Front Step Panel Board	1	\$78.50	\$78.50	11X
24	LH Front Door Frame	1	\$1,158.30	\$1,158.30	BMP ✓
25	LH Front Door Frame Weatherstrip	1	\$92.30	\$92.30	11X
26	LH Sliding Door	1	\$1,328.30	\$1,328.30	D.S ✓
27	LH Sliding Door Outer Handle	1	\$119.40	\$119.40	CNE ✓
28	LH Sliding Door -Front	1	566.00	566.00	D.S/CNE ✓
29	LH Sliding Door lock switch - Front	1	\$74.10	\$74.10	11X
30	LH Sliding Door Top Roller	1	\$55.10	\$55.10	11X
31	LH Sliding Door Centre Roller	1	\$122.00	\$122.00	11X
32	LH Sliding Door Bottom Roller	1	\$122.40	\$122.40	11X
33	LH Sliding Door Roller Trail	1	\$694.40	\$694.40	11X
34	LH Sliding Door Inner Trim Board	1	\$480.60	\$480.60	11X
35	LH Sliding Door Weather Strip	1	\$167.80	\$167.80	11X
36	LH Sliding Door Lock -Rear	1	\$234.20	\$234.20	11X
37	LH Rear Fender Panel	1	\$2,006.90	\$2,006.90	11X
38	LH Front Wheel Cap	1	\$161.50	\$161.50	11X

429.10

2727430
102
26546.87
50-30
271130
920097
212
7568

KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

RAGE

		Sub Total	\$12,119.70	
		Less 10%	\$1,211.97	
		Sub Total 1	\$10,907.73	
B.	S/Nett			
1	LH Front Door Company Reg Sticker	1	\$50.00	\$50.00
		Sub Total 2	\$50.00	
C.	Labour			
1	To panel beat, knock and straighten damaged panel and re-align the same		\$1,200.00	
2	To Check all necessary wiring and lighting		\$80.00	
	To Transfer Door Mech		\$120.00	
	To Remove Upholstery		\$300.00	
	To Transfer LH Sliding Door		\$120.00	
3	To rust proof all affected areas		\$60.00	
4	To spray paint the affected areas		\$1,800.00	
		Total Labour	\$3,680.00	
		Total Repair Cost	\$14,637.73	
	* The above quoted are exclusive of GST.			

Yours faithfully,

Kai
f KT Garage Pte Ltd

Surveyor's Details	
Name	maray klu
Contact	90296608
Survey Date	11/5/22
Recommend	Authorize / Not Authorize
Before Paint	Yes / No
Signature	AKH

DATE	Remark From Mr Tan
	Please arrange for survey asap

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorize
2/5/22 7350/
7 days.
Whiphe After repair
11/5/22

P-727430
102
P-6546.87
S.N-30
2-2630
9206.87
202
7365