

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Not Withheld

No. : 06577

Vehicle Insured : GV1400Z

Accident Date : 04-May-2022

11 Rm 810, 900

Date : 05-May-2022

Our Ref : 022069 (AIG) / CHAN

Recovery After Painting

PAGE : 1

OH SIEW HUI TERENCE
36 DA SILVA LANE
Singapore 549766

7 days

ESTIMATED COST OF REPAIR FOR TOYOTA PRIUS HYBRID 1.8 SLE983U

1 pc	Tail gate			<i>R</i>	1,159.90	<i>✓</i>
1 pc	Tail gate glass inner seal			<i>new</i>	107.10	<i>✓</i>
1 pc	Tail gate spoiler			<i>Sn</i>	1,044.30	<i>✓</i>
1 pc	Tail gate 3rd brake light			<i>Shorten</i>	203.40	<i>✓</i>
1 pc	Tail gate lower glass			<i>my cm</i>	688.80	<i>✓</i>
1 pc	Tail gate lower trim cover			<i>u.i.</i>	605.20	<i>✓</i>
1 pc	Tail gate inner trim cover				433.70	<i>✓</i>
1 pc	Tail gate rubber			<i>Rel/Dij</i>	387.30	<i>50/2m 793-65SN</i>
1 pc	Tail gate inner lock	<i>452.10</i>		<i>new</i>	495.40	<i>✓</i>
1 pc	Tail gate outer garnish			<i>CM</i>	685.70	<i>✓</i>
1 pc	Tail gate "PRIUS" emblem			<i>new</i>	72.10	<i>✓</i>
1 pc	Tail gate "HYBRID" plate			<i>new</i>	66.40	<i>✓</i>
1 pc	Tail gate logo			<i>new</i>	64.80	<i>✓</i>
2 pcs	Tail gate no.plate lamp		@ S\$ 92.20	<i>Sn</i>	184.40	<i>✓</i>
2 pcs	Taillamp	<i>501.30</i>	@ S\$ 554.20	<i>Od</i>	1,108.40	<i>✓</i>
2 pcs	Taillamp side garnish		@ S\$ 65.70	<i>R</i>	131.40	<i>✓</i>
1 pc	Rear end panel			<i>Diy</i>	592.20	<i>✓</i>
1 pc	End panel top garnish			<i>R</i>	233.80	<i>✓</i>
1 pc	Spare tyre panel			<i>Return</i>	969.90	<i>✓</i>
1 pc	Spare tyre top cover			<i>CM</i>	526.60	<i>✓</i>
1 pc	N/s spare tyre tool sponge			<i>CM</i>	460.60	<i>✓</i>
1 pc	O/s spare tyre tool sponge			<i>CM</i>	460.60	<i>✓</i>
1 pc	Rear bumper fascia	<i>485.60</i>		<i>R</i>	693.30	<i>✓</i>
2 pcs	Rear bumper side (lower)		@ S\$ 128.40	<i>R</i>	256.80	<i>✓</i>
1 pc	Rear bumper lower spoiler			<i>R</i>	482.20	<i>✓</i>
1 pc	Rear lower spoiler tow cover			<i>Od</i>	32.30	<i>✓</i>
1 pc	Rear bumper reinforcement			<i>R</i>	326.60	<i>✓</i>
1 pc	Rear bumper centre under cover			<i>CM</i>	255.40	<i>✓</i>
2 pcs	Rear bumper side under cover		@ S\$ 242.20		484.40	<i>✓</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GV1400Z

Page : 2

2 pcs Rear bumper lamp	218.20 <i>my car</i>	@ S\$398.70	797.40	✓
2 pcs Rear bumper side retainer		@ S\$109.90	219.80	✓
2 pcs Rear bumper nut & screw		@ S\$ 6.40	12.80	✓
1 pc Rear exhaust silencer box			1,738.50	✓
1 pc Rear exhaust heat seal			238.50	✓
1 pc Rear o/s blind spot sensor box			2,234.10	✓

18,454.10

Less 25% : 4,613.52

1 pc Tail gate centre chrome (set)	
1 pc End panel top garnish chrome	
2 pcs Rear bumper parking sensor(ctr	@ S\$200.00
2 pcs Rr bumper side parking sensor	@ S\$200.00
1 pc Rear bumper clip (set)	
1 pc Rear w/s glass sealant	
1 pc Rear no.plate with casing	
1 pc Tail gate open switch assy	
1 pc Rear bumper top chrome	
1 pc Rear bumper lower chrome	

	13,840.58	✓
<i>Ne</i>	80.00	sn
<i>Bu</i>	120.00	sn
<i>Del/sher</i>	400.00	sn
<i>shery</i>	400.00	sn
<i>Ne</i>	40.00	sn
<i>Ne</i>	100.00	sn
<i>Ne</i>	50.00	sn
<i>Im</i>	800.00	sn
<i>B</i>	155.00	sn
<i>cm</i>	150.00	sn

To remove & renew rear windscreen glass and conduct water leak test.

200.00 *180*

To remove roof lining, front and rear seats, trim board and carpet

180.00 *80*

To apply undersealing

100.00 *30*

To remove and renew exhaust silencer box

60.00 *4*

To putty and spray replaced parts

1,600.00 *1400*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

1,800.00 *900*

Total : S\$20,075.58

Singapore Dollars Twenty Thousand and Seventy Five and Cents Fifty Eight Only