

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKU7885B
Accident Date : 07-May-2022

Our Ref : 022078 (CHINA) / CHAN

YEO XUE WEI DANSON
BLK 7 THOMSON LANE
#31-05
Singapore 297725

No. : 06585

Date : 12-May-2022

PAGE : 1

*Not Authorized
11/12 @ 4150h
Presony After Paint
6day*

ESTIMATED COST OF REPAIR FOR V/W TOURAN SMU1214D

1 pc Front n/s fender
1 pc Front n/s door *1050*
1 pc Front n/s door rubber
2 pcs Front n/s door hinge
1 pc Rear n/s door *1050*
1 pc Rear n/s door rubber
1 pc Rear n/s fender
1 pc Rr n/s fender glass c/w mouldg
1 pc Rear n/s taillamp
1 pc Rear n/s bumper side retainer
1 pc N/s sport rim *1120*

Bl/way
R 450.00 X
1,050.00 ✓
M 220.00 ✓
R 240.00 X
R 1,050.00 ✓
M 250.00 ✓
R 1,550.00 X
M 250.00 X
M 350.00 X
M 90.00 X
M 1,120.00 ✓

6,620.00
Less 10% : 662.00

1 pc Rear n/s fender glass sealant

To check and adjust wheel alignment

To remove & renew n/s fender glass

To apply undersealing

To remove roof lining, front and
rear seats, trim board and carpet

5,958.00
M 60.00 sn X
65.00 *601*
M 120.00 X
60.00 ✓
120.00 *601*

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKU7885B

Page : 2

To putty and spray replaced parts

1000/-
1,200.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700/-
1,000.00

Total : S\$ 8,583.00
=====

Singapore Dollars Eight Thousand Five Hundred
and Eighty Three Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: