



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

MOTIVE Q PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

Not Authorized
LH
13/5/22
2/5 3000
4 days
why not why

S & S Facility Engineering Services
1 Sunview Road, #06-28, Eco-Tech@Sunview
Singapore 627615

Contact : 81888742

ESTIMATE

Code : C102037

Date in : 09/05/2022

Vehicle Num. : GBF8608P

Model : Toyota Hiace DX 3.0 M

Chassis/Eng# : KDH2010214895/1KD2680538

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Front bonnet R	1	1082.50	1,082.50 X
Front bumper Re	1	573.60	573.60 ✓
Front bumper fog lamp cover LH 11	1	59.80	59.80 X
Front bumper lower grille 11	1	188.70	188.70 X
Front bumper reinforcement 11	1	379.40	379.40 X
Front bumper side retainer MS ana	2	151.20	302.40 12C
Front corner panel LH TD	1	284.60	284.60 ✓
Front LH door R	1	1999.70	1,999.70 X
Front LH door handle 11	1	199.50	199.50 X
Front LH door hinges 11	2	116.90	233.80 X
Front LH door lock 11	1	613.30	613.30 X
Front LH door rubber 11	1	244.20	244.20 X
Front LH door side mirror 11	1	1272.70	1,272.70 X
Front LH headlamp ana	1 860.11	953.60	953.60 ✓
Front LH step garnish 11	1	171.90	171.90 X
Subtotal before discount			8,559.70
Percentage discount 25%			2,139.93
Sub-total 1			6,419.78
Company Stickers (Bonnet & Door) (SN)	1 111	320.00	320.00 ✓

Bumper clip (set) (sn)	1	35.00	35.00	✓
Front bumper lower skirting (SN)	1	450.00	450.00	✓
Front camera LH (SN)	1	380.00	380.00	✓
Front door ROC sticker (SN)	1	25.00	25.00	✓
Subtotal before discount			1,210.00	
Percentage discount 0%			0.00	
Sub-total 2			1,210.00	
Parts-total			7,629.78	✓

LABOUR

Description	Price
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	20 100.00
To diagnose, replace and/or repair to rectify front door electrical system for proper functioning	11 X 160.00
To transfer front door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	11 X 150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	600 1,400.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	500 1,200.00
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	20 150.00
Labour Total	3,160.00
Parts & Labour Total	10,789.78

P- 1869.57
257

P - 1402.13

S.N - 1210

L - 1140

3752.13

20%

3001.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: