PRS Rec. By: GQ | REF: CS3/ASM22004639/Gqy3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s LLH CAR SERVICES

of

Insured:

Policy No.

Claims No. S2M041EO

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: $11600

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: CB7266H Yr Regn: 27 Sep/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA / HIACE c.c 2982

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 393205 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KDH2230017328

Gen. Cond Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	18-05-2022

Survey held at W/S 12:15PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV: $6000/year x 11 year + $50k = $11600
	$2000 - $3000
20/05/22@2.09pm	revised to Cynthia Loh via Smart Claims.
20/05/22	Submit PRS.

Date/Time, File Pass to? : Preli. Report

1) 20/05 Typist : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: : Site Insp ($) : Interview ($) : Tech. Invs ($) : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL

Report Format: SMART CLAIMS - PRS

Lump Sum / UPD: